

Exhibit "B"

Site Testing Results **and Scope Quantities**

**Asbestos Survey for
Port Hueneme High School
500 West Bard Road
Oxnard, California 93033**

Prepared for:

Mr. Poul Hansen
Bond Project Manager
Oxnard Union High School

TC Project No. 103921



Mike Tabbara
CEO/President



Ivan Dean Meyers
CAC # 02-3128

Date:
July 8, 2020

Prepared by:

Tabbara Corporation
350 N. Lantana Street, Suite 224
Camarillo, California 93010



Tabbara Corporation

350 N. Lantana Street, Suite 224, Camarillo, CA 93010 Tel: 805-484-3388, Fax: 805-426-8119

July 8, 2020

Mr. Poul Hansen
Bond Project Manager
Oxnard Union High School District

TC JOB # 103921

RE: ASBESTOS SURVEY REPORT FOR
Port Hueneme High School
500 West Bard Road
Oxnard, California 93033

Dear Mr. Henson:

Attached is the Asbestos Survey Report for the above-referenced facility. The report includes an executive summary, management of asbestos, sampling and laboratory procedures, sample logs, and plans depicting approximate sample locations.

If you have any questions regarding this report, please call us at (805) 484-3388.

Sincerely,

Mahmoud Majdoub
Project Scientist

ASBESTOS SURVEY REPORT
PORT HUENEME HIGH SCHOOL
OXNARD, CA 93033

TABLE OF CONTENTS

- 1.0 EXECUTIVE SUMMARY
 - 2.0 REGULATIONS
 - 3.0 SAMPLING, LABORATORY PROCEDURES AND METHODS
 - 4.0 LIMITATIONS
 - 5.0 FINDINGS AND CONCLUSIONS
- PLANS DEPICTING SAMPLE LOCATIONS

APPENDICES

- A: LABORATORY ANALYTICAL RESULTS AND CHAIN OF CUSTODY DOCUMENTATION
- B: CERTIFICATIONS

1.0 EXECUTIVE SUMMARY

At the request of Oxnard Union High School District, Tabbara Corporation (TC) performed a full building survey on campus on many buildings between June 22 and July 7, 2020 for asbestos-containing materials (ACM) at Port Hueneme High School – Several Buildings located at 500 West Bard Road in Oxnard, California (Subject Site). The work was performed by Mr. Antonio Chavez, a Certified Site Surveillance Technician (CSST) #04-3632, under the guidance of Mr. Abbas Sam, a Certified Asbestos Consultant (CAC) #09-4551. The scope of work was conducted in compliance with current state and federal asbestos regulations. The survey included visual observation for ACM, sampling of suspect materials and laboratory analysis. Every effort was made to survey all accessible suspect materials. Additional suspect but un-sampled materials could be located between walls, in voids, or in other areas; caution should be exercised regarding these areas.

TC’s finding and conclusions are included in this report.

Bulk Sampling

TC’s technician collected a total of five hundred & seventy five (575) bulk samples to be analyzed by Polarized Light Microscopy (PLM).

Building A (Library):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Throughout	<1% Chrysotile	1,500 SF	Good

4 Transite Pipes were observed on top of the roof. This material is assumed to be positive.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile & Mastic, Drywall, Plaster, HVAC Duct Mastic Baseboard Mastic, Stucco, HVAC Duct Mastic, Gravel Roofing Composite and Penetration Mastic.

Building B (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

13 Transite Pipes were observed on top of the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile, Drywall, Plaster/Gypsum Composite, Baseboard Mastic, 12”X 12” Tan Floor Tile & Mastic, HVAC Duct Mastic, Stucco, Gravel Roofing Composite and Penetration Mastic.

Building C (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

14 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile, Drywall, Joint Compound, Baseboard Mastic, 12”X 12” Tan Floor Tile & Mastic, 12”x12” Gray Floor Tile & Mastic, Gravel Roofing Composite and Penetration Mastic.

Building D (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good
Black Mastic associated with 12” Gray Floor Tile	Classroom 10	3% Chrysotile	900 SF	Good

12 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”x12’ Random Hole Ceiling Tile, Drywall, Plaster/Drywall Composite, Baseboard Mastic, Plaster, 12”X 12” Gray Floor Tile, 12”x12” Tan Floor Tile and Mastic, Exterior Stucco, Gravel Roofing Composite and Penetration Mastic.

Building E (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closets and Ceilings	2% Chrysotile	2,500 SF	Good

8 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile with associated Mastic, Drywall, Plaster/Gypsum Composite, Baseboard Mastic, 12”X 12” White Floor Tile & Mastic, Exterior Stucco, Gravel Roofing Composite, Penetration Mastic and HVAC Duct Mastic.

Buildings F (Girls Locker Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

12 pipes were observed on the roof.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile, Drywall, Joint compound, Plaster, Baseboard Mastic, 12”x 12” Gray Floor Tile & Mastic, Exterior Stucco, Gravel Roofing Composite and Penetration Mastic.

Building G (Boys Locker Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

12 pipes were observed on the roof.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile, Drywall, Joint Compound, Plaster, Baseboard Mastic, 12”x12” Blue Floor Tile & Mastic, Stucco, Gravel Roofing Composite and Penetration Mastic.

Building H (Shop):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
9"x9" Brown Floor Tile	Room 89A & 89B and 88A (Storages)	<1% Chrysotile	300 SF	Good
Black Mastic associated with 9"x9" Floor Tile	Room 89A & 89B and 88A (Storages)	5% Chrysotile	300 SF	Good
Black Mastic associated with 12" Floor Tile	Room 89, 90 & 91	3% Chrysotile	4,950 SF	Good

7 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12"X 12" Ceiling Tiles and Mastic, 2'x4' Fissured Ceiling Panels, Drywall, Joint Compound, Baseboard Mastic, Carpet Mastic, 12"x12" Tan Floor Tile & Mastic, 12"x12" Gray Floor Tile Composite, Carpet Mastic, Gravel Roofing Composite and Penetration Mastic.

Building I (Cafeteria):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Stucco	Interior Walls	<1% Chrysotile	2,400 SF	Good
Stucco	Exterior	<1% Chrysotile	2,200 SF	Good

3 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile and Mastic, 2’x4’ Fissured Ceiling Panel, Drywall, Joint Compound, Baseboard Mastic, 12”X 12” Grey Floor Tile & Mastic, Gravel Roofing Materials, Penetration Mastic and HVAC Duct Mastic.

Building J (Band Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

1 pipe was observed on the roof.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile and Mastic, Drywall, Joint Compound, Baseboard Mastic, 12”x12” Tan Floor Tile, 12”x12” Gray Floor Tile Mastic associated with Floor Tile, Stucco, Gravel Roofing Composite and Penetration Mastic.

Building K (Administration):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Mastic associated with 12” Tan Floor Tile	Hall, Admin Area and Reception	2% Chrysotile	3,300 SF	Good
9”x9” Brown Floor Tile	Vault and Janitor Room	3% Chrysotile	160 SF	Good
Black Mastic associated with 9” Brown Floor Tile	Vault and Janitor Room	3% Chrysotile	160 SF	Good

2 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Fissured Acoustical Ceiling Tile & associate Mastic, Drywall Ceiling, Plaster Mastic associated with 4” Baseboard, 12” Tan Floor Tile, Stucco, Penetration Mastic and Gravel Roofing Composite.

Building M (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

8 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”x12 Acoustical Ceiling Tile with Mastic, Drywall (Ceiling) & Joint Compound (Ceiling), Plaster, Baseboard Mastic, 12”X 12” White Floor Tile & Mastic, Stucco, Gravel Roofing Composite and Penetration Mastic.

Building N (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classroom Heater Closet	<1% Chrysotile	1,300 SF	Good

13 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”x12” Random Hole Ceiling Tile, Drywall, Joint Compound, Plaster/Drywall Composite, Baseboard Mastic, 12”X 12” Tan Floor Tile & Mastic, Gravel Roofing Composite and Penetration Mastic.

Building O (Classrooms):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms	<1% Chrysotile	1,500SF	Good

2 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X 12” Ceiling Tile, 2’X4’ Ceiling Panel, Drywall, Baseboard Mastic, 12”X 12” Tan Floor Tile & Mastic, Gravel Roofing Materials and Penetration Mastic.

Building P (Gym):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility, or could not be representatively sampled. Such materials should be assumed to contain asbestos until they are confirmed to have no detection of asbestos

- Roofing Materials (Inaccessible and not in the scope)

Suspect materials that were sampled and found to have no concentration of asbestos included:

- Drywall, Select Joint Compound, Plaster, Baseboard Mastic, HVAC Duct Mastic, Gravel Roofing Composite and Penetration Mastic.

Building Q (Activity Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California:

Materials	Location	Results	SF	Condition
Stucco	Exterior Walls	<1% Chrysotile	3,000 SF	Good

4 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”X12” Ceiling Tile & Mastic, Drywall & Joint Compound, Plaster, Stucco, Gravel Roofing Composite, Penetration Mastic.

Building R (Weight Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

Materials	Location	Results	SF	Condition
Drywall/Joint Compound	Ceiling	<1% Chrysotile	3,375 SF	Good
Stucco	Exterior Walls	<1% Chrysotile	3,000 SF	Good

4 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- 12”x12” Random Hole Ceiling Tile & Mastic, Plaster, Stucco, Gravel Roofing and Penetration Mastic.

Building T (Pool Equipment):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

Suspect materials that were sampled and found to have no concentration of asbestos included:

- Gravel Roofing Composite, Penetration Mastic and HVAC Duct Mastic.

Asbestos Management

Asbestos is a hazardous substance. Its condition, handling and disposal are regulated by federal, state and local agencies. If ACCM is disturbed or appears to have become damaged, the condition must be reported to the appropriate supervisor. All asbestos abatement work must be performed in accordance with governing agency regulations. If any construction, maintenance, or remodeling is conducted in an area of the facility where there is the potential for employees to come into contact with, or release or disturb, asbestos or asbestos-containing construction materials, a sign with the following language must be posted: “CAUTION. ASBESTOS CANCER AND LUNG DISEASE HAZARD. DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT.”

TC recommends that one staff member be assigned as an Operations and Maintenance (O&M) Program Manager, who will develop and manage the program. The person should receive appropriate training and be charged with coordinating periodic O&M inspections. These inspections should include surveying all asbestos-containing building products in the facility. Defects such as signs of increased wear, water damage, vandalism and impact damage should be noted and repaired immediately. Construction or remodeling which occurs in the buildings should be reviewed by the O&M managers in the planning stage to see if preparatory abatement work will be required. A complete record should be maintained of all findings (including this report), procedures, and actions. This record should also contain names of technical advisors, inspectors, consultants, and all staff time, material and costs associated with asbestos control and abatement. In the future, if cost recovery is sought from the manufacturers, suppliers, or contractors, or in the event of litigation, this information will be required.

2.0 REGULATIONS

This section provides a summary of the federal and state regulations that apply to asbestos and asbestos-related work. The summary is not intended to be comprehensive or to define all regulatory requirements that may apply to Port Hueneme High located at 500 West Bard Road in Oxnard, California, or to persons who perform asbestos-related work in this facility.

2.1 U.S. Environmental Protection Agency

The U.S. Environmental Protection Agency (EPA) regulates environmental exposures to asbestos through two major pieces of legislation: The National Emission Standards for Hazardous Air Pollutants (NESHAP) under the Clean Air Act and the Asbestos Hazard Emergency Response Act (AHERA) under the Toxic Substances Control Act.

NESHAP, Part 61 of Title 40 of the Code of Federal Regulations (CFR), establishes standards by which asbestos-related work must be performed in order to prevent asbestos from being released into the environment. Some of the requirements include:

- Inspecting for asbestos before commencing a demolition or renovation project,
- Notifying the local NESHAP enforcement agency of all demolition work and asbestos abatement work,
- Training asbestos workers,
- Prohibiting visible emissions and requiring the use of wet methods, negative-pressure enclosures, labeling of waste, and proper handling methods from removal to disposal.

AHERA, Part 763 of 40 CFR, requires schools to inspect for asbestos, prepare management plans, to make notifications regarding the presence of asbestos, use air sampling to confirm proper asbestos removal, and use accredited personnel to perform asbestos-related activities. AHERA and subsequent related legislation established a nationwide program of training and certification required of asbestos professionals, including abatement contractors and workers, who perform work in schools. These requirements have been extended to include asbestos work performed in all public and private sector buildings.

2.2 Occupational Safety and Health

The Occupational Safety and Health Administration (OSHA), regulates occupational exposures to asbestos through the General Industry and Construction Industry asbestos standards (29 CFR 1910.1001 for GISO & 1926.1101 for construction work). These standards are designed to protect workers from asbestos exposure through a series of requirements based on exposures above the permissible exposure limit (PEL). These requirements include:

- Assuming that certain building materials contain asbestos and that buildings constructed prior to 1980 contain Asbestos Containing Construction Materials (ACCM).
- Implementing medical surveillance, respiratory protection, and training programs that include medical examinations, provision of respiratory and Personal Protective Equipment (PPE), and training of workers and supervisors for certain classes of work.

- Training persons who may be exposed to asbestos during their work.
- Using specific types of respirators dependent on the asbestos concentrations being generated.
- For asbestos related work activities work practices and equipment such as negative-pressure enclosures, wet methods, air filtration equipment, decontamination units, warning signs and labels, and waste containers.
- Collecting and analyzing air samples to evaluate potential worker exposures.
- Mandating contractor registration with and notification of asbestos work to the local OSHA enforcement agency.
- Notifying occupants for projects covered by the standard.

In California, the Department of Occupational Safety and Health (DOSH) enforces the OSHA regulations under Section 1529 & Section 5208 of Title 8 of the California Code of Regulations (CCR). DOSH also requires that asbestos consultants performing work in California be trained and certified.

2.3 Other Asbestos Regulations

Many other federal and state regulations that are designed to protect workers, building occupants, and consumers from exposures to hazardous materials also apply to asbestos, including hazard communication, hazardous waste operators and emergency responders, and safe workplace regulations. Some of these include:

- California Environmental Protection Agency-Cal/EPA regulates asbestos waste and requires manifests for transportation and disposal of hazardous asbestos waste (friable and contains greater than 1 percent asbestos). Cal/EPA also requires waste generators to obtain an identification number. Parts of the California Health and Safety Code require that occupants of buildings and consumers of certain products be notified of their contents and the health effects associated with exposures or consumption.
- Certain California regulations may also involve compliance for 0.1% (ACCM). Any contractor or employer (public or private) who engages in asbestos-related work as defined in Labor Code Section 6501.8 involving 100 square feet or more of asbestos-containing material must register with CAL-OSHA and is subject to the lower ACCM threshold.
- Contractors State License Board-The CSLB required that asbestos abatement contractors be licensed as general contractors and maintain an asbestos certification.
- State Board of Equalization-Generators of hazardous waste is required to obtain a tax identification number and pay tax on the amount by weight of waste disposed.
- California Highway Patrol/Department of Transportation-CHP requires that waste containers be properly labeled and that transporters be registered.

Other legislation regulating asbestos exposure in the workplace includes:

- California Health and Safety Code 25249 (Proposition 65)-Requires warnings to be given to individuals who enter a building known to contain asbestos, if such individuals are subject to an asbestos exposure and the building owner cannot demonstrate that significant risk does not exist.
- California Health and Safety Code 25915 et seq. (Connelly Bill)-Requires the owner of any building constructed prior to 1979, who knows that the building contains ACCM, to provide notice to all occupants of that building of the presence and location of known ACCM. Building owners are required to give this notice within 15 days of receipt.

2.4 Notifications

Prior to renovation or demolition work, the contractor should inquire about any abatement notification requirements with the Local Air Pollution Control District.

3.0 SAMPLING, LABORATORY PROCEDURES & METHODS

3.1 Laboratory Procedures and Analysis

Bulk samples were analyzed by PLM using EPA Method 600/R-93/116, July 1993, in accordance with 40 CFR 763, Subpart F, Appendix A (AHERA), and if applicable, the Point Count Method 600/R-93/116, July 1993, by Micron Environmental Laboratories, located at 3635 Lexington Ave in El Monte, California. Bulk samples of suspected ACM were examined under a stereomicroscope to identify suspect fibers. A polarized light microscope equipped with a dispersion staining objective lens was used to determine which of the suspect fibers are asbestos. The various asbestos minerals were identified on the basis of their unique optical characteristics. Reported asbestos percentages were based on visual volume estimates.

3.2 Inspection Procedures - General

The building spaces were surveyed for the presence of suspect ACM that may contain more than one tenth of one percent asbestos. The suspect materials identified were described and categorized into homogeneous areas. Homogeneous areas consist of suspect materials that are identical in color, appearance, pattern, texture and date of installation. For the purposes of this survey, identified homogenous areas were confined to the building. Samples were collected according to OSHA (29 CFR 1926.1011) dated August 10, 1994 (Revised September 12, 1995).

3.3 Choosing Sample Locations

Samples of suspect ACM were collected in accordance with AHERA to determine whether the materials contain asbestos. Samples were not collected from homogeneous materials when the inspector determined that the material was non-ACM (such as foam, glass, wood, rubber, ceramic tile).

3.4 Sampling Methods

Samples were obtained with a stainless steel knife to penetrate a material without creating excessive dust. Except for joint compound, the knife was utilized to cut, rather than scratch a sample from the surface of suspect materials in an effort to obtain a sample that was representative of all layers of the material. The sampled area was pre-wetted to minimize or reduce fiber generation during the sampling process. Damaged or inconspicuous areas were sampled wherever practical.

TC's sampling procedures incorporate the use of plastic Ziploc[™] bags, labeled with black permanent markers per a unique numbering sequence. One label with the sample number was placed on the sample bag, and a second description was placed on the bulk sample log. Information about the sample, including the sample type, location and condition, was noted on the sheet as each sample was collected.

4.0 LIMITATIONS

This survey was planned and implemented on the basis of a mutually agreed scope of work. The survey was conducted in conformance with generally accepted current standards for identifying and evaluating asbestos in construction materials. TC uses only qualified professionals to perform building surveys; reasonable effort was made to survey accessible suspect materials. Additional suspect but un-sampled materials could be located between walls, in voids, or in other inaccessible areas; caution should be exercised regarding these areas. TC cannot warrant that these buildings do not contain ACM in locations other than those noted in this report.

TC's assessment of the risk of exposure to airborne asbestos fibers followed generally accepted protocols and is based on conditions at the time of the survey. TC is not responsible for changes in conditions or accepted protocols subsequent to our site visit.

5.0 FINDINGS & CONCLUSIONS

ASBESTOS SURVEY REPORT **CHANNEL ISLAND HIGH SCHOOL** **OXNARD, CALIFORNIA 93033**

A full buildings material survey was performed Between June 23rd and July 7th, 2020 for asbestos-containing materials (ACM)) at Port Hueneme High School – Several Buildings located at 500 West Bard Road in Oxnard, California (Subject Site). The work was performed by Mr. Antonio Chavez, a Certified Site Surveillance Technician (CSST) #04-3632, under the guidance of Mr. Abbas Sam, a Certified Asbestos Consultant (CAC) #09-4551.

Asbestos was detected in the following materials, in the buildings listed below, that were sampled by TC.

Building A (Library):

Materials	Location	Results	SF	Condition
Joint Compound	Throughout	<1% Chrysotile	1,500 SF	Good

4 Transite Pipes were observed on top of the roof. This material is assumed to be positive.

Building B (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

13 Transite Pipes were observed on top of the roof. This material is assumed to be asbestos containing material.

Building C (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

14 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building D (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good
Black Mastic associated with 12” Gray Floor Tile	Classroom 10	3% Chrysotile	900 SF	Good

12 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building E (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closets and Ceilings	2% Chrysotile	2,500 SF	Good

8 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Buildings F (Girls Locker Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

12 pipes were observed on the roof.

Building G (Boys Locker Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

12 pipes were observed on the roof.

Building H (Shop):

Materials	Location	Results	SF	Condition
9"x9" Brown Floor Tile	Room 89A & 89B and 88A (Storages)	<1% Chrysotile	300 SF	Good
Black Mastic associated with 9"x9" Floor Tile	Room 89A & 89B and 88A (Storages)	5% Chrysotile	300 SF	Good
Black Mastic associated with 12" Floor Tile	Room 89, 90 & 91	3% Chrysotile	4,950 SF	Good

7 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material

Building I (Cafeteria):

Materials	Location	Results	SF	Condition
Stucco	Interior Walls	<1% Chrysotile	2,400 SF	Good
Stucco	Exterior	<1% Chrysotile	2,200 SF	Good

3 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material

Building J (Band Room):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

The following suspect materials were not sampled as part of the scope of this project because of inaccessibility (Wrapped with metal). Such materials should be assumed to contain asbestos until they are confirmed by lab analysis to have no detection of asbestos.

1 pipe was observed on the roof. This material is assumed to be asbestos containing material

Building K (Administration):

Materials	Location	Results	SF	Condition
Mastic associated with 12" Tan Floor Tile	Hall, Admin Area and Reception	2% Chrysotile	3,300 SF	Good
9"x9" Brown Floor Tile	Vault and Janitor Room	3% Chrysotile	160 SF	Good
Black Mastic associated with 9" Brown Floor Tile	Vault and Janitor Room	3% Chrysotile	160 SF	Good

2 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building M (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms Heater Closet	<1% Chrysotile	1,200 SF	Good

8 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building N (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classroom Heater Closet	<1% Chrysotile	1,300 SF	Good

13 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building O (Classrooms):

Materials	Location	Results	SF	Condition
Joint Compound	Classrooms	<1% Chrysotile	1,500SF	Good

2 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building P (Gym):

Construction materials that contain asbestos fibers in percentages greater than one tenth of one percent (> 0.1%) **were not found**. Materials with levels of asbestos greater than 0.1% are regulated by government agencies in the state of California.

Building Q (Activity Room):

Materials	Location	Results	SF	Condition
Stucco	Exterior Walls	<1% Chrysotile	3,000 SF	Good

4 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Building R (Weight Room):

Materials	Location	Results	SF	Condition
Drywall/Joint Compound	Ceiling	<1% Chrysotile	3,375 SF	Good
Stucco	Exterior Walls	<1% Chrysotile	3,000 SF	Good

4 Transite pipes were observed on the roof. This material is assumed to be asbestos containing material.

Note: All Transite Pipes located on the roof of the buildings listed above are assumed to be positive. The presence of this material was visually observed in some areas. Additional suspect but un-sampled materials could be located between walls, in voids, or in other inaccessible areas; caution should be exercised regarding these areas.

APPENDIX A
LABORATORY ANALYSIS RESULTS
AND
CHAIN OF CUSTODY DOCUMENTATION



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 9, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420075
Client Ref.: 103921 / Building A (Library)
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 24 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420075

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building A (Library) Microscopist: Vy Phan
Oxnard Union HS / Port Hueneme HS

July 9, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/26/2020
Date Received: 6/30/2020
Date Analyzed: 7/9/2020
No. Samples: 24

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899069	12" Random hole ACT Library white/brown	No	90% Cellulose 10% Organic Binders	X
2 899070	12" Random hole ACT Book storage office white/brown	No	90% Cellulose 10% Organic Binders	
3 899071	12" Random hole ACT Book storage white/brown	No	90% Cellulose 10% Organic Binders	
4 899072	Mastic with 12" ACT Book storage brown	No	100% Organic Binders	
5 899073	Mastic with 12" ACT Book storage brown	No	100% Organic Binders	
6 899074	Mastic with 12" ACT Library book storage brown	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 9, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420075

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899075	HVAC Duct mastic Book storage / Store room grey	No	20% Mineral Filler 80% Organic Binders	
8 899076	HVAC Duct mastic Book storage / Store room grey	No	20% Mineral Filler 80% Organic Binders	
9 899077	HVAC Duct mastic Book storage / Store room grey	No	20% Mineral Filler 80% Organic Binders	
10 899078	Drywall ceiling Library storage room white	No	7% Cellulose 93% Mineral Filler	
11 899079	Drywall ceiling Book storage office white	No	7% Cellulose 93% Mineral Filler	
12 899080	Drywall ceiling Southeast office, heater closet white	No	7% Cellulose 93% Mineral Filler	
13 899081	Joint compound SE Classroom beige	Yes	<1% Chrysotile 99% Mineral Filler	X
14 899082	Joint compound SE Classroom beige	Yes	<1% Chrysotile 99% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 9, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420075

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899083	Joint compound NW Classroom beige	Yes	<1% Chrysotile 99% Mineral Filler	
16 899084	Plaster East office grey	No	100% Mineral Filler	
17 899085	Plaster Faculty room grey	No	100% Mineral Filler	
18 899086	Plaster Book storage / Condor room grey	No	100% Mineral Filler	
19 899087	Mastic associated with 4" BB SE Classroom beige	No	10% Mineral Filler 90% Organic Binders	
20 899088	Mastic associated with 4" BB East office beige	No	10% Mineral Filler 90% Organic Binders	
21 899089	Mastic associated with 4" BB Library beige	No	10% Mineral Filler 90% Organic Binders	
22 899090	Stucco Exterior walls grey	No	100% Mineral Filler	

Sample Summary Results


Exhibit B

Date: Jul 9, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420075

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899091	Stucco Exterior walls grey	No	100% Mineral Filler	
24 899092	Stucco Exterior walls grey	No	100% Mineral Filler	X

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420086
Client Ref.: 103921 Oxnard Union HS
Port Hueneme- Bldg. A

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 9 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420086

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: Danny Lu
Port Hueneme- Bldg. A

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/8/2020
Date Analyzed: 7/15/2020
No. Samples: 9

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900222	Gravel Roofing Composite Roof black	No	20% Cellulose 20% Fibrous Glass 20% Mineral Filler 40% Organic Binders	
02 900223	Gravel Roofing Composite Roof black	No	20% Cellulose 20% Fibrous Glass 20% Mineral Filler 40% Organic Binders	
03 900224	Gravel Roofing Composite Roof black	No	20% Cellulose 20% Fibrous Glass 20% Mineral Filler 40% Organic Binders	
04 900226	Penetration Mastic Roof black	No	10% Cellulose 90% Organic Binders	
05 900227	Penetration Mastic Roof black	No	10% Cellulose 90% Organic Binders	
06 900228	Penetration Mastic Roof black	No	10% Cellulose 90% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420086

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
07 900229	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
08 900230	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
09 900231	HVAC Duct Mastic Roof grey	No	100% Organic Binders	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04


TABBARA CORPORATION

Date: 6/26/20
Client: Oxnard Union HS
Site: Port Hueneme HS - Bldg A (Library)
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Library		~ 7,700 #		N	G
2	↓	Book storage office		↓		↓	↓
3	↓	Book storage		↓		↓	↓
4	Mastic with 12" ACT	Book storage		~ 1,000 #			
5	↓	↓		↓			
6	↓	Library book storage		↓			
7	HVAC Duct Mastic	Book storage / store room		~ 100 LF			
8	↓	↓		↓			
9	↓	↓		↓			
10	Daywall ceiling	Library storage room		~ 1,500 #			
11	↓	Book storage office		↓			
12	↓	Booth End office	Heater duct	↓		↓	
13	Joint compound	SE Classroom				F	
14	↓	↓				↓	
15	↓	NW Classroom				↓	

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

Rec: 3. Gomez 6/30/20 2:08 PM


TABBARA CORPORATION

Date: 6/26/20
Client: Oxnard Union HS
Site: Port Hueneume HS - Bldg A (Library)
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Plaster	East office				N	G
17	↓	Faculty Room				↓	↓
18	↓	Book storage / Conden Room				↓	↓
19	Mastic associated with	SE Classroom				↓	↓
20	4" BBS	East office				↓	↓
21	↓	Library				↓	↓
22	Stucco	Exterior walls				↓	↓
23	↓	↓				↓	↓
24	↓	↓				↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

TABBARA CORPORATION

Date:	7/1/20
Client:	Oxnard Union HS
Site:	Port Hueneeme - Bldg A (Library)
Project #:	103921
Inspector(s):	A. Sam / M. Majdoub

* Preliminary results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 4	ND	N	G
2	↓	↓		↓	ND	↓	↓
3	↓	↓		↓	ND	↓	↓
4	Penetration Mastic			~ 10 #	ND	↓	↓
5	↓	↓		↓	ND	↓	↓
6	↓	↓		↓	ND	↓	↓
7	HVAC Duct Mastic			~ 20 LF	ND	↓	↓
8	↓	↓		↓	ND	↓	↓
9	↓	↓		↓	ND	↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 B. Gary 7/8/20 12:46



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420076
Client Ref.: 103921 / Building B
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 30 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420076

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building B Microscopist: Vy Phan
Oxnard Union HS / Port Hueneme HS

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/22/2020
Date Received: 6/30/2020
Date Analyzed: 7/9/2020
No. Samples: 30

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899093	12x12" Random hole ACT Classroom 15 white/brown	No	90% Cellulose 10% Organic Binders	
2 899094	12x12" Random hole ACT Classroom 12 white/brown	No	90% Cellulose 10% Organic Binders	
3 899095	12x12" Random hole ACT Classroom 8 white/brown	No	90% Cellulose 10% Organic Binders	
4 899096	Drywall Classroom 8, heater closet white	No	10% Cellulose 90% Mineral Filler	
5 899097	Drywall Classroom 13, heater closet white	No	10% Cellulose 90% Mineral Filler	
6 899098	Drywall Classroom 5, heater closet white	No	10% Cellulose 90% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420076

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899099	Joint compound Classroom 8 beige	Yes	<1% Chrysotile 99% Mineral Filler	X
8 899100	Joint compound Classroom 13 beige	Yes	<1% Chrysotile 99% Mineral Filler	
9 899101	Joint compound Classroom 8 beige	Yes	<1% Chrysotile 99% Mineral Filler	
10 899102	Mastic associated with 4" BB Classroom 8 beige	No	100% Organic Binders	
11 899103	Mastic associated with 4" BB Classroom 12 beige	No	100% Organic Binders	
12 899104	Mastic associated with 4" BB Classroom 15 beige	No	100% Organic Binders	
13 899105	12" Resilient floor tile - tan Classroom 8 white	No	30% Mineral Filler 70% Organic Binders	X
14 899106	12" Resilient floor tile - tan Classroom 12 white	No	30% Mineral Filler 70% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420076

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899107	12" Resilient floor tile - tan Classroom 15 white	No	30% Mineral Filler 70% Organic Binders	
16 899108	Mastic associated with #13 Classroom 8 black	No	100% Organic Binders	
17 899109	Mastic associated with #14 Classroom 12 black	No	100% Organic Binders	
18 899110	Mastic associated with #15 Classroom 15 black	No	100% Organic Binders	
19 899111	Plaster Janitor room wall grey	No	100% Mineral Filler	X
20 899112	Plaster Janitor room ceiling grey	No	100% Mineral Filler	
21 899113	Plaster Janitor room ceiling grey	No	100% Mineral Filler	
22 899114	Drywall (above plaster) Janitor room ceiling white	No	10% Cellulose 90% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420076

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899115	Drywall (above plaster) Janitor room ceiling white	No	10% Cellulose 90% Mineral Filler	
24 899116	Drywall (above plaster) Janitor room ceiling white	No	10% Cellulose 90% Mineral Filler	
25 899117	Exterior stucco grey	No	100% Mineral Filler	
26 899118	Exterior stucco grey	No	100% Mineral Filler	
27 899119	Exterior stucco grey	No	100% Mineral Filler	
28 899120	HVAC Duct mastic grey	No	10% Mineral Filler 90% Organic Binders	
29 899121	HVAC Duct mastic grey	No	10% Mineral Filler 90% Organic Binders	X
30 899122	HVAC Duct mastic grey	No	10% Mineral Filler 90% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420076

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: Vy Phan

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420087
Client Ref.: 103921 Oxnard Union HS
Port Hueneme HS- Bldg. B

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420087

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: David Espique
Port Hueneme HS- Bldg. B

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/8/2020
Date Analyzed: 7/15/2020
No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900231	Gravel Roofing Composite Roof black/grey	No	5% Cellulose 5% Fibrous Glass 40% Mineral Filler 50% Organic Binders	
02 900232	Gravel Roofing Composite Roof black/grey	No	5% Cellulose 5% Fibrous Glass 40% Mineral Filler 50% Organic Binders	
03 900233	Gravel Roofing Composite Roof black/grey	No	5% Cellulose 5% Fibrous Glass 40% Mineral Filler 50% Organic Binders	
04 900234	Penetration Mastic Roof black	No	10% Cellulose 15% Mineral Filler 75% Organic Binders	
05 900235	Penetration Mastic Roof black	No	10% Cellulose 15% Mineral Filler 75% Organic Binders	X
06 900236	Penetration Mastic Roof black	No	10% Cellulose 15% Mineral Filler 75% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Espique

Micron Ref. No.: 14420087

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: David Espique

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	6/22/20
Client:	Concord Union HS
Site:	Port Hueneme HS - Building B
Project #:	103921
Inspector(s):	A. Sam / T. Kajdaub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" x 12" Random Hole ACT	Classroom / 15		~ 12,950 lb		N	G
2	↓	↓ / 12		↓		↓	↓
3	↓	↓ / 8		↓		↓	↓
4	Daywall	Classroom / 8	Heater duct	~ 1,200 lb		↓	↓
5	↓	↓ / 13	↓	↓		↓	↓
6	↓	↓ / 5	↓	↓		↓	↓
7	Joint Compound	Classroom / 8	↓	↓		F	↓
8	↓	↓ / 13	↓	↓		↓	↓
9	↓	↓ / 8	↓	↓		↓	↓
10	Mastic associated with 1/2" BB	Classroom 8		~ 1,680 lb		N	↓
11	↓	↓ 12		↓		↓	↓
12	↓	↓ 15		↓		↓	↓
13	12" Resilient Floor Tile	Classroom 8		~ 12,960 lb		↓	↓
14	Tam	↓ 12		↓		↓	↓
15	↓	↓ 15		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

Rec: *[Signature]*
 Rec: *[Signature]* 6/30/20 2:08 pm

TABBARA CORPORATION


Date:	6/22/20
Client:	Oxnard Union HS
Site:	Port Huememe HS
Project #:	103921
Inspector(s):	A. Sam / M. Rajdaub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic associated with # 13	Classroom 8		2-13		N	G
17	↓ # 14	↓ 12		↓		↓	↓
18	↓ # 15	↓ 15		↓		↓	↓
19	Plaster	Janitor Room	Wall	~ 300 SF		↓	↓
20	↓	↓	Ceiling	↓		↓	↓
21	↓	↓	Ceiling	↓		↓	↓
22	Daywall (above Plaster)	↓	Ceiling	~ 300 SF		↓	↓
23	↓	↓	↓	↓		↓	↓
24	↓	↓	↓	↓		↓	↓
25	Exterior Stucco			~ #		↓	↓
26	↓			↓		↓	↓
27	↓			↓		↓	↓
28	HVAC Duct Mastic			~ 100 LF		↓	↓
29	↓			↓		↓	↓
30	↓			↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____



TABBARA CORPORATION

Date:	7/1/20
Client:	oxnard Union HS
Site:	Pat Huememe HS - Bldg B
Project #:	103921
Inspector(s):	A. Sam / M. Hujdan

* Preliminary Results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results X	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 10	NA	N	G
2					NA		
3					NA		
4	Penetration Mastic			~ 20 ct	ND		
5					ND		
6					ND		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: *[Handwritten Signature]*
 B. Gamble 12:40 pm 7/8/20



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420077
Client Ref.: 103921 / Building C
Oxnard Union HS District / Port Hueneme

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 30 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420077

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building C
Oxnard Union HS District / Port Hueneme

Microscopist: Daniel Gamez

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/23/2020

Date Received: 6/30/2020

Date Analyzed: 7/9/2020

No. Samples: 30

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899123	12" Resilient floor tile - tan Classroom 16 beige	No	100% Mineral Filler	
2 899124	12" Resilient floor tile - tan Classroom 22 beige	No	100% Mineral Filler	
3 899125	12" Resilient floor tile - tan Classroom 24 beige	No	100% Mineral Filler	
4 899126	Black mastic associated with #1 Classroom 16 black	No	100% Organic Binders	
5 899127	Black mastic associated with #2 Classroom 22 black	No	100% Organic Binders	
6 899128	Black mastic associated with #3 Classroom 24 black	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420077

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899129	Mastic associated with 4" black baseboard Classroom 20 beige	No	100% Organic Binders	
8 899130	Mastic associated with 4" black baseboard Classroom 20 beige	No	100% Organic Binders	
9 899131	Mastic associated with 4" black baseboard Classroom 20 beige	No	100% Organic Binders	
10 899132	Mastic associated with 4" beige baseboard Classroom 16 yellow	No	100% Organic Binders	
11 899133	Mastic associated with 4" beige baseboard Classroom 22 yellow	No	100% Organic Binders	
12 899134	Mastic associated with 4" beige baseboard Classroom 24 yellow	No	100% Organic Binders	
13 899135	12" Gray resilient floor tile Classroom 20 grey	No	100% Mineral Filler	
14 899136	12" Gray resilient floor tile Classroom 20 grey	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420077

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899137	12" Gray resilient floor tile Classroom 20 grey	No	100% Mineral Filler	
16 899138	Mastic associated with #13 Classroom 20 yellow	No	100% Organic Binders	
17 899139	Mastic associated with #14 Classroom 20 yellow	No	100% Organic Binders	X
18 899140	Mastic associated with #15 Classroom 20 yellow	No	100% Organic Binders	
19 899141	Drywall Classroom 16, heater closet white	No	100% Mineral Filler	
20 899142	Drywall Classroom 22, heater closet white	No	100% Mineral Filler	
21 899143	Drywall Classroom 20, heater closet white	No	100% Mineral Filler	
22 899144	Joint compound Classroom 16, heater closet beige	Yes	<1% Chrysotile 99% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420077

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899145	Joint compound Classroom 22, heater closet beige	Yes	<1% Chrysotile 99% Mineral Filler	
24 899146	Joint compound Classroom 20, heater closet white	No	100% Mineral Filler	X
25 899147	12" Random hole ACT Classroom 22 brown	No	100% Cellulose	
26 899148	12" Random hole ACT Classroom 20 brown	No	100% Cellulose	
27 899149	12" Random hole ACT Classroom 16 brown	No	100% Cellulose	
28 899150	Exterior stucco beige/grey	No	100% Mineral Filler	
29 899151	Exterior stucco beige/grey	No	100% Mineral Filler	
30 899152	Exterior stucco beige/grey	No	100% Mineral Filler	X

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420077

Cust ID No.

Asbestos

Detected


Analytical Results

Q.C.

Micron ID No.

Sample Description / Color

Microscopist: _____



The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420088
Client Ref.: 103921 Oxnard HS
Port Hueneme- Bldg. C

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/15/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420088

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard HS Microscopist: Carlo Gamez
Port Hueneme- Bldg. C

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/15/2020
Date Analyzed: 7/15/2020
No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900237	Gravel Roofing Composite Roof black	No	30% Cellulose 20% Fibrous Glass 30% Mineral Filler 20% Organic Binders	
02 900238	Gravel Roofing Composite Roof black	No	30% Cellulose 20% Fibrous Glass 30% Mineral Filler 20% Organic Binders	
03 900239	Gravel Roofing Composite Roof black	No	30% Cellulose 20% Fibrous Glass 30% Mineral Filler 20% Organic Binders	
04 900240	Penetration Mastic Roof black	No	20% Mineral Filler 80% Organic Binders	
05 900241	Penetration Mastic Roof black	No	20% Mineral Filler 80% Organic Binders	
06 900242	Penetration Mastic Roof black	No	20% Mineral Filler 80% Organic Binders	X

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Carlo Gamez

Micron Ref. No.: 14420088

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: Carlo G. Gamez

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	6/23/20
Client:	Oxnard Union HS District
Site:	Port Hueneeme - Building C
Project #:	103921
Inspector(s):	A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition	
1	12" Resilient Floor Tile	Classroom 16		~ 10,320 #		N	G	
2	Tan	22		↓		↓	↓	
3		24						
4	Black Mastic associated / 1	Classroom 16						
5	2	22						
6	3	24						
7	Mastic associated with 4" Black	Classroom 20						~ 140 LF
8	Baseboard							
9								
10	Mastic associated with 4" BB	Classroom 16						~ 1,440 LF
11	BB	22						
12		24						
13	12" Gray Resilient Floor Tile	Classroom 20						~ 1,080 #
14		20						
15		20						

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

Rec: B. Garmey 6/30/20 2:08 pm

TABBARA CORPORATION

Exhibit B

14420077

Date:	6/23/20
Client:	Oxnard Union HS District
Site:	Port Hueneme - Building C
Project #:	103921
Inspector(s):	A. Sam / M. Hajdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic associated with #13	Classroom 20		R-13		N	
17	↓	↓		↓		↓	
18	↓	↓		↓		↓	
19	Drywall	Classroom 16	Heater Duct	~ 1,200 #			
20	↓	22	↓	↓		↓	
21	↓	20	↓	↓		↓	
22	Joint Compound	16	↓	↓		F	
23	↓	22	↓	↓		↓	
24	↓	20	↓	↓		↓	
25	12" Random Hole ACT	Classroom 22		~ 10,320 #		N	
26	↓	20	↓	↓		↓	
27	↓	16	↓	↓		↓	
28	Exterior Stucco			~ #			
29	↓			↓		↓	
30	↓			↓		↓	

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 Rec: B. Goring 6/30/20 2:08 pm


TABBARA CORPORATION

Date:	7/1/20
Client:	Oxnard Union HS District
Site:	Port Hueneme - Building C
Project #:	103921
Inspector(s):	A. Sam / M. Rajdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	Gravel Roofing Composite	Roof		~		N	G
2	↓	↓				↓	↓
3							
4	Penetration Mastic			~30 #			
5	↓	↓		↓		↓	↓
6	↓	↓					

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

B. [unclear] 7/8/20 12:46



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 9, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420078
Client Ref.: 103921 Oxnard Union HS District
Port Hueneme HS - Bldg. D

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 34 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
BG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420078

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS District Microscopist: Carlo Gamez
Port Hueneme HS - Bldg. D

July 9, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/23/2020

Date Received: 6/30/2020

Date Analyzed: 7/8/2020

No. Samples: 34

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 899153	12" Random Hole ACT Classroom 35 offwhite, brown	No	95% Cellulose 3% Mineral Filler 2% Organic Binders	
02 899154	12" Random Hole ACT Classroom 29 offwhite, brown	No	95% Cellulose 3% Mineral Filler 2% Organic Binders	
03 899155	12" Random Hole ACT Classroom 33 offwhite, brown	No	95% Cellulose 3% Mineral Filler 2% Organic Binders	
04 899156	Drywall Classroom 29 Heater Closet white	No	3% Cellulose 2% Fibrous Glass 90% Mineral Filler 5% Organic Binders	
05 899157	Drywall Classroom 26 Heater Closet white	No	3% Cellulose 2% Fibrous Glass 90% Mineral Filler 5% Organic Binders	
06 899158	Drywall Classroom 36 Heater Closet white	No	3% Cellulose 2% Fibrous Glass 90% Mineral Filler 5% Organic Binders	

Sample Summary Results

Date: Jul 9, 2020

Microscopist: Carlo Gamez

Micron Ref. No.: 14420078

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
07 899159	Joint Compound Classroom 29 Heater Closet beige	Yes	<1% Chrysotile 2% Cellulose 90% Mineral Filler 7% Organic Binders	
08 899160	Joint Compound Classroom 26 Heater Closet beige	Yes	<1% Chrysotile 2% Cellulose 90% Mineral Filler 7% Organic Binders	
09 899161	Joint Compound Classroom 36 Heater Closet beige	Yes	<1% Chrysotile 2% Cellulose 90% Mineral Filler 7% Organic Binders	X
10 899162	12" Grey RFT Composite Classroom 33 grey, white	No	2% Fibrous Glass 90% Mineral Filler 8% Organic Binders	
11 899163	12" Grey RFT Composite Classroom 33 grey, white	No	2% Fibrous Glass 90% Mineral Filler 8% Organic Binders	
12 899164	12" Grey RFT Composite Classroom 33 grey, white	No	2% Fibrous Glass 90% Mineral Filler 8% Organic Binders	
13 899165	Mastic associated w/ #10 Classroom 33 yellow	No	3% Mineral Filler 97% Organic Binders	
Layer 1				
13 899166	Mastic associated w/ #10 Classroom 33	Yes	3% Chrysotile 7% Mineral Filler 90% Organic Binders	X
Positive Stop Layer 2	black			

Sample Summary Results

Exhibit B

Date: Jul 9, 2020

Microscopist: Carlo Gamez

Micron Ref. No.: 14420078

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
14 899167	Mastic associated w/ #11 Classroom 33 yellow	No	3% Mineral Filler 97% Organic Binders	
Layer 1				
15 899169	Mastic associated w/ #12 Classroom 33 yellow	No	3% Mineral Filler 97% Organic Binders	
Layer 1				
16 899171	Mastic associated w/ 4" Black BB Classroom 33 white	No	2% Synthetic 3% Mineral Filler 95% Organic Binders	
17 899172	Mastic associated w/ 4" Black BB Classroom 33 white	No	2% Synthetic 3% Mineral Filler 95% Organic Binders	
18 899173	Mastic associated w/ 4" Black BB Classroom 33 white	No	2% Synthetic 3% Mineral Filler 95% Organic Binders	
19 899174	Tan 12" Resilient Floor Tile Classroom 26 white	No	95% Mineral Filler 5% Organic Binders	
20 899175	Tan 12" Resilient Floor Tile Classroom 29 white	No	95% Mineral Filler 5% Organic Binders	
21 899176	Tan 12" Resilient Floor Tile Classroom 36 white	No	95% Mineral Filler 5% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 9, 2020

Microscopist: Carlo Gamez

Micron Ref. No.: 14420078

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
22 899177	Black Mastic associated w/ #18 Classroom 26 black	No	3% Mineral Filler 97% Organic Binders	
23 899178	Black Mastic associated w/ #19 Classroom 29 black	No	3% Mineral Filler 97% Organic Binders	
24 899179	Black Mastic associated w/ #20 Classroom 36 black	No	3% Mineral Filler 97% Organic Binders	X
25 899180	Mastic w/ 4" Baseboard Classroom 26 white	No	3% Mineral Filler 97% Organic Binders	
26 899181	Mastic w/ 4" Baseboard Classroom 28 white	No	3% Mineral Filler 97% Organic Binders	
27 899182	Mastic w/ 4" Baseboard Classroom 36 beige	No	8% Mineral Filler 92% Organic Binders	
28 899183	Exterior Stucco white, grey	No	98% Mineral Filler 2% Organic Binders	
29 899184	Exterior Stucco white, grey	No	98% Mineral Filler 2% Organic Binders	X

Sample Summary Results

Exhibit B

Date: Jul 9, 2020

Microscopist: Carlo Gamez

Micron Ref. No.: 14420078

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
30 899185	Exterior Stucco white, grey	No	98% Mineral Filler 2% Organic Binders	
31 899186	Plaster / Drywall Composite Office Room Wall grey	No	2% Cellulose 95% Mineral Filler 3% Organic Binders	
32 899187	Plaster / Drywall Composite Office Room Wall grey	No	2% Cellulose 95% Mineral Filler 3% Organic Binders	
33 899188	Plaster / Drywall Composite Office Room Ceiling grey	No	2% Cellulose 95% Mineral Filler 3% Organic Binders	

Microscopist: Carlo G. Gamez

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420089
Client Ref.: 103921 Oxnard Union HS
Port Hueneme HS- Bldg D

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420089

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: David Espique
Port Hueneme HS- Bldg D

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020

Date Received: 7/8/2020

Date Analyzed: 7/15/2020

No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900243	Gravel Roofing Composite Roof grey/black	No	10% Cellulose 5% Fibrous Glass 45% Mineral Filler 40% Organic Binders	
02 900244	Gravel Roofing Composite Roof grey/black	No	10% Cellulose 5% Fibrous Glass 45% Mineral Filler 40% Organic Binders	
03 900245	Gravel Roofing Composite Roof grey/black	No	10% Cellulose 5% Fibrous Glass 45% Mineral Filler 40% Organic Binders	
04 900246	Penetration Mastic Roof grey/black	No	10% Cellulose 30% Mineral Filler 60% Organic Binders	X
05 900247	Penetration Mastic Roof grey/black	No	10% Cellulose 30% Mineral Filler 60% Organic Binders	
06 900248	Penetration Mastic Roof grey/black	No	10% Cellulose 30% Mineral Filler 60% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Espique

Micron Ref. No.: 14420089

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: David Espique

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Exhibit B

14420078

Date:	6/23/20
Client:	Oxnard Union HS District
Site:	Port Huememe HS - Bldg D
Project #:	103921
Inspector(s):	A. Sam / M. Hajdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Classroom 35		~10,320 #		N	G
2	↓	↓ 29		↓		↓	↓
3	↓	↓ 33		↓		↓	↓
4	Daywall	Classroom/29	Heater closed	~1,200 #			
5	↓	↓ /26		↓			
6	↓	↓ /36		↓		↓	
7	Joint Compound	Classroom/29				F	
8	↓	↓ /26		↓		↓	
9	↓	↓ /36		↓		↓	
10	12" Gray RFT Composite	Classroom 33		~900 #		N	
11	↓	↓		↓		↓	
12	↓	↓		↓		↓	
13	Mastic associated with # 10	↓		↓		↓	
14	↓	↓ # 11		↓		↓	
15	↓	↓ # 12		↓		↓	

NA = Not
 ND = Not
 N = Negative

Friability Codes: N = Non-Friable; F = Friable
 Condition Codes: G = Good; F = Fair; P = Poor

[Signature]
 REC: [Signature] 6/30/20 2:08 PM

TABBARA CORPORATION

Exhibit B

14420076

Date:	6/23/20
Client:	Oxnard Union HS District
Site:	Port Huememe - Bldg D
Project #:	103921
Inspector(s):	A. Sam / M. Tajdani

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic associated with 4" Black	Classroom # 33		~ 140 LF		N	G
17	BB	↓		↓		↓	↓
18	↓	↓		↓		↓	↓
19	Tan Resilient Floor Tile	Classroom # 26		~ 9,460 #		↓	↓
20	↓	# 29		↓		↓	↓
21	↓	# 36		↓		↓	↓
22	Black Mastic associated with	# 18		↓		↓	↓
23	with	# 19		↓		↓	↓
24	↓	# 20		↓		↓	↓
25	Mastic with 4" Baseboard	Classroom # 26		~ 1,540 LF		↓	↓
26	↓	# 28		↓		↓	↓
27	↓	# 36		↓		↓	↓
28	Exterior Stucco						
29	↓						
30	↓						

NA = Not
 ND = Not
 N = Negative

Friability Codes: N = Non-Friable; F = Friable
 Condition Codes: G = Good; F = Fair; P = Poor

[Signature]
 Rec: Jo Gomez 6/30/20 2:08

TABBARA CORPORATION


Date: 7/1/20
 Client: Oxnard Union HS
 Site: Port Huememe HS - Bldg D
 Project #: 103921
 Inspector(s): A. Sam / M. Mujica

* Preliminary Result

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results *	Friability	Condition
1	Gravel Roofing Composite	Roof		~ #	ND		
2					ND		
3					ND		
4	Penetration Mastic			~ 20 #	ND		
5					ND		
6					ND		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 B. Gray 12:46 7/8/20



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420079
Client Ref.: 103921 / Building E
Oxnard Union HS / Port Hueneme

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 40 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420079

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building E
Oxnard Union HS / Port Hueneme

Microscopist: David Soliman

July 10, 2020

Mike Tabbara

Tabbara Corporation

350 N. Lantana St., Suite 224

Camarillo, CA 93010

Date Collected: 6/24/2020

Date Received: 6/30/2020

Date Analyzed: 7/9/2020

No. Samples: 40

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899186	12" Random hole ACT Classroom 45 beige/tan	No	80% Cellulose 20% Organic Binders	X
2 899187	12" Random hole ACT Classroom 39 beige/tan	No	80% Cellulose 20% Organic Binders	
3 899188	12" Random hole ACT Classroom 46A beige/tan	No	80% Cellulose 20% Organic Binders	
4 899189	Mastic associated with 12" ACT Classroom beige	No	20% Mineral Filler 80% Organic Binders	
Layer 1				
4 899190	Mastic associated with 12" ACT Classroom brown	No	100% Organic Binders	
Layer 2				
5 899191	Mastic associated with 12" ACT beige	No	20% Mineral Filler 80% Organic Binders	
Layer 1				

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420079

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
5 899192	Mastic associated with 12" ACT brown	No	100% Organic Binders	
Layer 2				
6 899193	Mastic associated with 12" ACT brown	No	20% Mineral Filler 80% Organic Binders	
7 899194	Drywall Classroom 41, heater closet white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
8 899195	Drywall Classroom 39, heater closet white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
9 899196	Drywall Classroom 43, heater closet white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
10 899197	Joint compound Classroom 41 white/brown Sample appears to be drywall	No	3% Cellulose 97% Mineral Filler	
11 899198	Joint compound Classroom 39 beige	Yes	2% Chrysotile 98% Mineral Filler	X
13 899199	Plaster Janitor room white No drywall in sample	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420079

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
14 899200	Plaster Janitor room white No drywall in sample	No	100% Mineral Filler	
15 899201	Plaster Janitor room white No drywall in sample	No	100% Mineral Filler	
16 899202	Drywall Room 43A ceiling white	No	2% Cellulose 1% Fibrous Glass 97% Mineral Filler	
17 899203	Drywall Room 43A ceiling white/brown	No	5% Cellulose 1% Fibrous Glass 94% Mineral Filler	
18 899204	Drywall Room 46A ceiling white/brown	No	5% Cellulose 1% Fibrous Glass 94% Mineral Filler	
19 899205	Joint compound Room 43A ceiling white	No	100% Mineral Filler	
20 899206	Joint compound Room 43A ceiling white	No	100% Mineral Filler	
21 899207	Joint compound Room 46A ceiling beige	Yes	2% Chrysotile 98% Mineral Filler	X

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420079

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
22 899208	12" Fissured ACT Room 43 grey/white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	
23 899209	12" Fissured ACT Room 43 grey/white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	
24 899210	12" Fissured ACT Room 43 grey/white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	
25 899211	Mastic associated with 4" BB Room 46 offwhite	No	100% Mineral Filler	
26 899212	Mastic associated with 4" BB Room 41 offwhite	No	100% Mineral Filler	
27 899213	Mastic associated with 4" BB Room 43 offwhite	No	100% Mineral Filler	
28 899214	12x12" White RFT Room 39 white	No	30% Mineral Filler 70% Organic Binders	X
29 899215	12x12" White RFT Room 43 white	No	30% Mineral Filler 70% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420079

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
30 899216	12x12" White RFT Room 46 white	No	30% Mineral Filler 70% Organic Binders	
31 899217	Black mastic associated with #28 black	No	100% Organic Binders	
32 899218	Black mastic associated with #29 black	No	100% Organic Binders	
33 899219	Black mastic associated with #30 black	No	100% Organic Binders	
34 899220	Exterior stucco grey	No	100% Mineral Filler	
34 899221	Texture coat light grey	No	100% Mineral Filler	
35 899222	Exterior stucco grey	No	100% Mineral Filler	
35 899223	Texture coat light grey	No	100% Mineral Filler	

Sample Summary Results


Exhibit B

Date: Jul 10, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420079

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
36 899224	Exterior stucco grey	No	100% Mineral Filler	
36 899225	Texture coat light grey	No	100% Mineral Filler	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420090
Client Ref.: 103921 Oxnard Union HSD
Port Hueneme HS - Bldg E

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 9 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NO



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420090

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HSD Microscopist: Danny Lu
Port Hueneme HS - Bldg E

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020

Date Received: 7/8/2020

Date Analyzed: 7/14/2020

No. Samples: 9

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900249	Gravel Roofing Composite Roof black	No	20% Cellulose 10% Fibrous Glass 20% Mineral Filler 50% Organic Binders	
2 900250	Gravel Roofing Composite Roof black	No	20% Cellulose 10% Fibrous Glass 20% Mineral Filler 50% Organic Binders	
3 900251	Gravel Roofing Composite Roof black	No	20% Cellulose 10% Fibrous Glass 20% Mineral Filler 50% Organic Binders	X
4 900252	Penetration Mastic Roof black	No	20% Cellulose 80% Organic Binders	
5 900253	Penetration Mastic Roof black	No	20% Cellulose 80% Organic Binders	
6 900254	Penetration Mastic Roof black	No	20% Cellulose 80% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420090

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900255	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
8 900256	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
9 900257	HVAC Duct Mastic Roof grey	No	100% Organic Binders	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 6/24/20
Client: Oxnard Union HS
Site: Port Hueneeme - Building E
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Classroom 45		~ 11,110 #		N	G
2	↓	↓ 39		↓		↓	↓
3	↓	↓ 46 A		↓		↓	↓
4	Mastic associated with 12" ACT	Classroom		~ 1,000 #			
5	↓ 12" ACT			↓			
6	↓ 12" ACT			↓			
7	Daywall	Classroom 41	Heater Cabinet	~ 1,100 #			
8	↓	↓ 39		↓			
9	↓	↓ 43		↓			
10	Joint Compound	Classroom 41				F	
11	↓	↓ 39		↓		↓	
12	↓	↓ 43		↓		↓	
13	Plaster / Daywall Composite	Janitor Room		~ 2,000 #		N	
14	↓	↓		↓		↓	↓
15	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: *[Signature]*

REC: *[Signature]* 6/30/20 2:08 pm


TABBARA CORPORATION

Date: 6 / 1 / 20
Client: Oxnard Union HS
Site: Port Hueneeme - Building E
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Dry wall	Room 43A	Ceiling	~ 1,000 lb		N	G
17	↓	↓ 43A	↓	↓		↓	↓
18	↓	↓ 46A	↓	↓		↓	↓
19	Joint compound	Classroom 43A	↓	↓		F	↓
20	↓	↓ 43A	↓	↓		↓	↓
21	↓	↓ 46A	↓	↓		↓	↓
22	12" Fissured ACT	Classroom 43		~ 1085 lb		N	↓
23	↓	↓		↓		↓	↓
24	↓	↓		↓		↓	↓
25	Mastic associated with 4" BB	Classroom 46		~ 1,800 LF		↓	↓
26	↓	Classroom 41		↓		↓	↓
27	↓	Classroom 43		↓		↓	↓
28	12" x 12" White RFT	Classroom 39		~ 12,900		↓	↓
29	↓	↓ 43		↓		↓	↓
30	↓	↓ 46		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

Rec: B. Gannay 6/30/20 2:08


TABBARA CORPORATION

Date: 6 / 1 / 20
Client: Oxnard Union HS
Site: Port Hueneeme - Building E
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
31	Black Mastic asphalt / 28					N	G
32	↓ / 29					↓	↓
33	↓ / 30					↓	↓
34	Exterior Stucco					↓	↓
35	↓					↓	↓
36	↓					↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

Rec: B. Gomez 6/30/20 2:08

TABBARA CORPORATION

Exhibit B

14420090


Date:	7/1/20
Client:	Oxnard Union HS
Site:	Pat Huememe HS - Bldg E
Project #:	103921
Inspector(s):	A. Sam / M. Hijian

* Preliminary Results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results*	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 10	ND		
2	↓	↓		↓	ND		
3	↓	↓		↓	ND		
4	Penetration Mastic	↓		~ 15 #	ND		
5	↓	↓		↓	ND		
6	↓	↓		↓	ND		
7	HVAC Duct Mastic	↓		15 LF	ND		
8	↓	↓		↓	ND		
9	↓	↓		↓	ND		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 7/8/20 12:46



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420091
Client Ref.: 103921 Building F (Girl's Locker)
Oxnard Union HS / Port Hueneme

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 33 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420091

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Building F (Girl's Locker) Microscopist: Daniel Gamez
Oxnard Union HS / Port Hueneme

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/30/2020
Date Received: 7/8/2020
Date Analyzed: 7/10/2020
No. Samples: 33

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900258	12" Random hole ACP Office yellow	No	100% Cellulose	
2 900259	12" Random hole ACP Office yellow	No	100% Cellulose	
3 900260	12" Random hole ACP Office yellow	No	100% Cellulose	
4 900261	Drywall Locker's ceiling white	No	100% Mineral Filler	
5 900262	Drywall Locker's ceiling white	No	100% Mineral Filler	X
6 900263	Drywall Locker's ceiling white	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420091

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900264	Joint compound Locker's ceiling beige	No	100% Mineral Filler	
8 900265	Joint compound Locker's ceiling beige	No	100% Mineral Filler	
9 900266	Joint compound Locker's ceiling beige	No	100% Mineral Filler	
10 900267	Plaster SE Lockers beige	No	100% Mineral Filler	
11 900268	Plaster NE Lockers beige	No	100% Mineral Filler	X
12 900269	Plaster First aid office / Storage beige	No	100% Mineral Filler	
13 900270	Mastic with 4" BB (Tan) First aid office / Storage yellow	No	100% Organic Binders	
14 900271	Mastic with 4" BB (Tan) First aid office / Storage yellow	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420091

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900272	Mastic with 4" BB (Tan) First aid office / Storage yellow	No	100% Organic Binders	
16 900273	4" Tan baseboard First aid office / Storage beige	No	100% Organic Binders	
17 900274	4" Tan baseboard First aid office / Storage beige	No	100% Organic Binders	
18 900275	4" Tan baseboard First aid office / Storage beige	No	100% Organic Binders	
19 900276	12" Grey floor tile First aid office / Storage beige	No	100% Mineral Filler	
20 900277	12" Grey floor tile First aid office / Storage beige	No	100% Mineral Filler	
21 900278	12" Grey floor tile First aid office / Storage beige	No	100% Mineral Filler	
22 900279	Mastic associated with #19 First aid office / Storage yellow	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420091

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 900280	Mastic associated with #20 First aid office / Storage yellow	No	100% Organic Binders	
24 900281	Mastic associated with #21 First aid office / Storage yellow	No	100% Organic Binders	
25 900282	Exterior stucco beige/grey	No	100% Mineral Filler	
26 900283	Exterior stucco beige/grey	No	100% Mineral Filler	X
27 900284	Exterior stucco beige/grey	No	100% Mineral Filler	
28 900285	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
29 900286	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
30 900287	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	

Sample Summary Results

Exhibit B


Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420091

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
31 900288	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	X
32 900289	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
33 900290	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	

Microscopist: _____



The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneeme - Bldg F (Girls Locker)
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACP	office		~ 600#		N	G
2	↓	↓		↓		↓	↓
3	↓	↓		↓		↓	↓
4	Drywall	Locker's Ceiling		~ 4,600#		↓	↓
5	↓	↓		↓		↓	↓
6	↓	↓		↓		↓	↓
7	Joint Compound	↓		↓		F	↓
8	↓	↓		↓		↓	↓
9	↓	↓		↓		↓	↓
10	Plaster	SE Lockers		~ 6000#		N	↓
11	↓	NE Lockers		↓		↓	↓
12	↓	First Aid office/Storage		↓		↓	↓
13	Mastic with 4" BB (Tan)	↓		~ 80 LF		↓	↓
14	↓	↓		↓		↓	↓
15	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 7/8/20 12:46

TABBARA CORPORATION

Exhibit B

14420091

Date: 6/30/20
 Client: Oxnard Union HS
 Site: Port Hueneeme - Bldg F
 Project #: 103921
 Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition	
16	4" Tan Baseboard	First Aid office / storage		R-13		N	G	
17	↓							
18	↓							
19	12" Gray Floor Tile				~ 200 #			
20	↓							
21	↓							
22	Mastic associated with #19							
23	↓							
24	↓							
25	Exterior Stucco							
26	↓							
27	↓							
/	/	/	/	/	/	/	/	
/	/	/	/	/	/	/	/	

Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 legative

Signature: _____

[Handwritten Signature]
 7/8/20


TABBARA CORPORATION

Date:	7/2/20
Client:	Oxnard Union HS Union
Site:	Port Hueneme HS - Bldg F
Project #:	103921
Inspector(s):	A Sam / T. Rydamb

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
28	Gravel Roofing Composite	Roof					
29	↓	↓					
30							
31	Penetration Mastic			~ 15 #			
32	↓	↓		↓			
33							

NA = Not Analyzed, **Friability Codes:** Nf = Non-Friable; F = Friable
 ND = Not Detected, **Condition Codes:** G = Good; Fr = Fair; P = Poor
 N = Negative

Signature:  July 7/8/20



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420092
Client Ref.: 103921 Building G (Boy's Locker)
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 29 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420092

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Building G (Boy's Locker) Microscopist: Danny Lu
Oxnard Union HS / Port Hueneme HS

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/30/2020
Date Received: 7/8/2020
Date Analyzed: 7/10/2020
No. Samples: 29

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900291	12" Random hole ACT brown	No	90% Cellulose 10% Organic Binders	
2 900292	12" Random hole ACT brown	No	90% Cellulose 10% Organic Binders	
3 900293	12" Random hole ACT brown	No	90% Cellulose 10% Organic Binders	
4 900294	Drywall / Joint Compound Locker room wall pink/white	No	10% Cellulose 90% Mineral Filler	
5 900295	Drywall / Joint Compound Locker room wall pink/white	No	10% Cellulose 90% Mineral Filler	
6 900296	Drywall / Joint Compound Locker room ceiling pink/white	No	10% Cellulose 90% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420092

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900297	Drywall / Joint Compound Locker room ceiling pink/white	No	10% Cellulose 90% Mineral Filler	
8 900298	Drywall / Joint Compound Locker room ceiling pink/white	No	10% Cellulose 90% Mineral Filler	
9 900299	Plaster Office G05 grey/white	No	100% Mineral Filler	X
10 900300	Plaster Office G05 grey/white	No	100% Mineral Filler	
11 900301	Plaster Office G14 grey/white	No	100% Mineral Filler	
12 900302	Mastic associated with 4" baseboard Coaches office tan	No	10% Cellulose 90% Organic Binders	
13 900303	Mastic associated with 4" baseboard Coaches office tan	No	10% Cellulose 90% Organic Binders	
14 900304	Mastic associated with 4" baseboard Coaches office tan	No	10% Cellulose 90% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420092

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900305	12" Blue floor tile Coaches office blue	No	100% Organic Binders	
16 900306	12" Blue floor tile Coaches office blue	No	100% Organic Binders	
17 900307	12" Blue floor tile Coaches office blue	No	100% Organic Binders	
18 900308	Mastic associated with #15 Coaches office black/yellow	No	10% Cellulose 90% Organic Binders	
19 900309	Mastic associated with #16 Coaches office black/yellow	No	10% Cellulose 90% Organic Binders	X
20 900310	Mastic associated with #17 Coaches office black/yellow	No	10% Cellulose 90% Organic Binders	
21 900311	Stucco Exterior walls beige/grey	No	100% Mineral Filler	
22 900312	Stucco Exterior walls grey/white	No	100% Mineral Filler	X

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420092

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 900313	Stucco Exterior walls grey/brown	No	100% Mineral Filler	
24 900314	Gravel roofing composite Roof black	No	20% Cellulose 10% Fibrous Glass 30% Mineral Filler 40% Organic Binders	
25 900315	Gravel roofing composite Roof black	No	20% Cellulose 10% Fibrous Glass 30% Mineral Filler 40% Organic Binders	
26 900316	Gravel roofing composite Roof black	No	20% Cellulose 10% Fibrous Glass 30% Mineral Filler 40% Organic Binders	
27 900317	Penetration mastic Roof black	No	10% Cellulose 90% Organic Binders	
28 900318	Penetration mastic Roof black	No	10% Cellulose 90% Organic Binders	
29 900319	Penetration mastic Roof black	No	10% Cellulose 90% Organic Binders	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 6/30/20
 Client: Oxnard Union HS
 Site: Pat Huememe HS - Bldg G (Boys Locker)
 Project #: 103921
 Inspector(s): A. Sam / M. Hijar

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT			~ 600 #		N	G
2	↓ Dry wall / Joint compound ↓ ↓ ↓ ↓ Plaster ↓ Mastic associated with 4" Baseboard ↓ 12" Blue Floor Tile					↓	↓
3							
4		Locker Room Wall		~ 4,900 lb			
5							
6		Locker Room Ceiling					
7							
8							
9		office G05		~ 5,000 #			
10							
11		office G14					
12		Coach's office		~ 90 LF			
13							
14							
15		Coach's office		~ 200 #			

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: *[Signature]*

[Signature] 7/8/20 12:46

TABBARA CORPORATION

Date:	6/30/20
Client:	Donald Union HS
Site:	Pat Huene HS - Bldg G (Boys Locker)
Project #:	103921
Inspector(s):	A. Sam / M. Huidobro

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	12" Blue Floor Tile	Coach's office		R-15		N	G
17	↓	↓		↓		↓	↓
18	Mastic associated with # 15						
19	↓ # 16						
20	↓ # 17						
21	Stucco	Exterior Walls					
22	↓	↓					
23	↓	↓					
24	Gravel Roofing Composite	Roof					
25	↓	↓					
26	↓	↓					
27	Penetration Mastic						
28	↓	↓					
29	↓	↓					

NA = Not Analyzed, **Friability Codes:** Nf = Non-Friable; F = Friable
 ND = Not Detected, **Condition Codes:** G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 7/8/20



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420093
Client Ref.: 103921 Oxnard Union HS
Port Hueneme - Bldg. H

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 64 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
BG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420093

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: David Soliman
Port Hueneme - Bldg. H

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/30/2020

Date Received: 7/8/2020

Date Analyzed: 7/9/2020

No. Samples: 64

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900320	12" Random Hole ACT Room 83 offwhite, beige	No	90% Cellulose 10% Mineral Filler	X
02 900321	12" Random Hole ACT Room 85 offwhite, beige	No	90% Cellulose 10% Mineral Filler	
03 900322	12" Random Hole ACT Room 88 offwhite, beige	No	90% Cellulose 10% Mineral Filler	
04 900323	2'x4' Fissured ACP Room 90 grey, white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	
05 900324	2'x4' Fissured ACP Room 91 grey, white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	
06 900325	2'x4' Fissured ACP Room 91 grey, white	No	79% Cellulose 1% Fibrous Glass 20% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
07 900326	Drywall Room 86B white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
08 900327	Drywall Room 86B white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
09 900328	Drywall Room 86B white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
10 900329	Joint Compound Room 86B white	No	100% Mineral Filler	X
11 900330	Joint Compound Room 86B white	No	100% Mineral Filler	
12 900331	Joint Compound Room 86B white	No	100% Mineral Filler	
13 900332	Mastic associated w/ 4" BB Room 81A Office beige	No	100% Organic Binders	
14 900333	Mastic associated w/ 4" BB Room 85 beige	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900334	Mastic associated w/ 4" BB Room 87 beige	No	100% Organic Binders	
16 900335	Mastic associated w/ 6" BB Room 83A white	No	10% Mineral Filler 90% Organic Binders	
Layer 1				
16 900336	Mastic associated w/ 6" BB Room 83A offwhite	No	10% Mineral Filler 90% Organic Binders	
Layer 2				
17 900337	Mastic associated w/ 6" BB Room 84A white	No	10% Mineral Filler 90% Organic Binders	
Layer 1				
17 900338	Mastic associated w/ 6" BB Room 84A offwhite	No	10% Mineral Filler 90% Organic Binders	X
Layer 2				
18 900339	Mastic associated w/ 6" BB Room 84A white	No	10% Mineral Filler 90% Organic Binders	
Layer 1				
18 900340	Mastic associated w/ 6" BB Room 84A offwhite	No	10% Mineral Filler 90% Organic Binders	
Layer 2				
19 900341	9"x9" Brown Floor Tile Room 89 Storage grey	Yes	<1% Chrysotile 39% Mineral Filler 60% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
20 900342	9"x9" Brown Floor Tile Room 88A Storage grey	Yes	<1% Chrysotile 39% Mineral Filler 60% Organic Binders	
21 900343	9"x9" Brown Floor Tile Room 88A Storage grey	Yes	<1% Chrysotile 39% Mineral Filler 60% Organic Binders	
22 900344	Black Mastic associated w/ #19 Room 89 Storage black	Yes	5% Chrysotile 95% Organic Binders	
25 900345	12" Tan Floor Tile Room 86 white	No	30% Mineral Filler 70% Organic Binders	
26 900346	12" Tan Floor Tile Room 81A white	No	30% Mineral Filler 70% Organic Binders	
27 900347	12" Tan Floor Tile Room 81A white	No	30% Mineral Filler 70% Organic Binders	X
28 900348	Black Mastic associated w/ #25 Room 86 black	No	100% Organic Binders	
29 900349	Black Mastic associated w/ #26 Room 81A black	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
30 900350	Black Mastic associated w/ #27 Room 81A black	No	100% Organic Binders	
31 900351	12" Brown Floor Tile Composite Room 89 grey	No	30% Mineral Filler 70% Organic Binders	
31 900352	Mastic Room 89 black, yellow	Yes	3% Chrysotile 97% Organic Binders	
32 900353	12" Brown Floor Tile Composite Room 89 grey	No	30% Mineral Filler 70% Organic Binders	
33 900354	12" Brown Floor Tile Composite Room 89 grey	No	30% Mineral Filler 70% Organic Binders	
34 900355	12" Grey Floor Tile Composite Room 83A grey	No	30% Mineral Filler 70% Organic Binders	
34 900356	Mastic Room 83A yellow	No	100% Organic Binders	X
34 900357	Leveling Compound Room 83A grey	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
35 900358	12" Grey Floor Tile Composite Room 84A grey	No	30% Mineral Filler 70% Organic Binders	
35 900359	Mastic Room 84A yellow	No	100% Organic Binders	
35 900360	Leveling Compound Room 84A grey	No	100% Mineral Filler	
35 900361	Mastic Room 84A black	No	100% Organic Binders	
36 900362	12" Grey Floor Tile Composite Room 84A grey	No	30% Mineral Filler 70% Organic Binders	
36 900363	Mastic Room 84A yellow	No	100% Organic Binders	
36 900364	Leveling Compound Room 84A grey	No	100% Mineral Filler	
36 900365	Mastic Room 84A black	No	100% Organic Binders	X

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
37 900366	Carpet Mastic (Yellow) Room 83D Storage yellow	No	100% Organic Binders	
37 900367	Tile Room 83D Storage offwhite	No	30% Mineral Filler 70% Organic Binders	
37 900368	Mastic Room 83D Storage black	No	100% Organic Binders	
38 900369	Mastic Room 83D Storage yellow	No	100% Organic Binders	
38 900370	Tile Room 83D Storage offwhite	No	30% Mineral Filler 70% Organic Binders	
38 900371	Mastic Room 83D Storage black	No	100% Organic Binders	
39 900372	Mastic Room 83D Storage yellow	No	100% Organic Binders	
39 900373	Tile Room 83D Storage offwhite	No	30% Mineral Filler 70% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
39 900374	Mastic Room 83D Storage black	No	100% Organic Binders	X
40 900375	Gravel Roofing Composite Roof black, grey	No	10% Fibrous Glass 10% Synthetic 50% Mineral Filler 30% Organic Binders	
41 900376	Gravel Roofing Composite Roof black, grey	No	10% Fibrous Glass 10% Synthetic 50% Mineral Filler 30% Organic Binders	
42 900377	Gravel Roofing Composite Roof black, brown	No	20% Cellulose 10% Fibrous Glass 40% Mineral Filler 30% Organic Binders	
43 900378	Penetration Mastic Roof black, red	No	5% Cellulose 10% Mineral Filler 85% Organic Binders	
44 900379	Penetration Mastic Roof black, white	No	5% Cellulose 50% Mineral Filler 45% Organic Binders	
45 900380	Penetration Mastic Roof black, brown, white	No	5% Cellulose 45% Mineral Filler 50% Organic Binders	
46 900381	HVAC Duct Mastic Roof grey	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420093

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
47 900382	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
48 900383	HVAC Duct Mastic Roof grey, offwhite	No	10% Mineral Filler 90% Organic Binders	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneeme - Bldg H
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Room 83				N	G
2	↓	Room 85				↓	↓
3	↓	Room 88				↓	↓
4	2'x4' Fissured ACP	Room 90				↓	↓
5	↓	Room 91				↓	↓
6	↓	Room 91				↓	↓
7	Dry wall	Room 86 B	~			↓	↓
8	↓	↓				↓	↓
9	↓	↓				↓	↓
10	Joint compound	↓				F	↓
11	↓	↓				↓	↓
12	↓	↓				↓	↓
13	Mastic associated with 4" BB	Room 81A office				N	↓
14	↓	85				↓	↓
15	↓	87				↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: *[Handwritten Signature]*
 30/6/20 7/8/20 12:46

TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneume - Bldg H
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic associated with 6" BB	Room 83 A				N	G
17	↓	Room 84 A				↓	↓
18	↓	Room 84 A					
19	9" x 9" Brown Floor Tile	Room 89 Storage					
20	↓	Room 88A Storage					
21	↓	Room 88A Storage					
22	Black Mastic with /# 19	Room 89 Storage					
23	↓ /# 20	Room 88A Storage					
24	↓ /# 21	Room 88A Storage					
25	12" Tan Floor Tile	Room 86					
26	↓	↓ 81A					
27	↓	↓ 81A					
28	BLK Mastic with /# 25	Room 86					
29	↓ /# 26	↓ 81A					
30	↓ /# 27	↓ 81A					

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 36 12:46


TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneeme - Bldg H
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
31	12" Brown Floor Tile	Room 89				N	G
32	Composite	↓				↓	↓
33							
34	12" Gray Floor Tile	Room 83 A					
35	Composite	↓ 84 A					
36		↓ 84 A					
37	Carpet Mastic (yellow)	Room 83 D	Storage				
38		↓	↓			↓	↓
39							
40	Gravel Roofing Composite	Roof		~ 10			
41		↓					
42							
43	Penetration Mastic			~ 15			
44							
45							

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 B. Majdoub 7/8/20



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420080
Client Ref.: 103921 / Building I
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 33 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420080

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building I Microscopist: Vy Phan
Oxnard Union HS / Port Hueneme HS

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/29/2020
Date Received: 6/30/2020
Date Analyzed: 7/9/2020
No. Samples: 33

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899222	12" Fissured ACT Cafeteria white/brown	No	90% Mineral Filler 10% Organic Binders	X
2 899223	12" Fissured ACT Cafeteria white/brown	No	90% Mineral Filler 10% Organic Binders	
3 899224	12" Fissured ACT Kitchen white/brown	No	90% Mineral Filler 10% Organic Binders	
4 899225	Mastic associated with 12 ACT Cafeteria brown	No	100% Organic Binders	
5 899226	Mastic associated with 12 ACT Cafeteria brown	No	100% Organic Binders	
6 899227	Mastic associated with 12 ACT Kitchen brown	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420080

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899228	2x4' Fissured ACP Lounge grey/white	No	70% Cellulose 25% Mineral Filler 5% Organic Binders	
8 899229	2x4' Fissured ACP Lounge grey/white	No	70% Cellulose 25% Mineral Filler 5% Organic Binders	
9 899230	2x4' Fissured ACP Lounge grey/white	No	70% Cellulose 25% Mineral Filler 5% Organic Binders	
10 899231	Drywall Cafeteria white	No	10% Cellulose 90% Mineral Filler	
11 899232	Drywall Cafeteria white	No	10% Cellulose 90% Mineral Filler	
12 899233	Drywall Kitchen white	No	10% Cellulose 90% Mineral Filler	
13 899234	Joint compound Cafeteria white	No	100% Mineral Filler	
14 899235	Joint compound Cafeteria white	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420080

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899236	Joint compound Kitchen white	No	100% Mineral Filler	X
16 899237	Mastic associated with 4" baseboard Cafeteria beige	No	20% Mineral Filler 80% Organic Binders	
17 899238	Mastic associated with 4" baseboard Cafeteria beige	No	20% Mineral Filler 80% Organic Binders	
18 899239	Mastic associated with 4" baseboard Lounge beige	No	20% Mineral Filler 80% Organic Binders	
19 899240	Plaster Lounge grey	No	100% Mineral Filler	
20 899241	Plaster Kitchen grey	No	100% Mineral Filler	
21 899242	Plaster Kitchen grey	No	100% Mineral Filler	
22 899243	12" Gray floor tile Lounge light blue	No	30% Mineral Filler 70% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420080

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899244	12" Gray floor tile Cafeteria light blue	No	30% Mineral Filler 70% Organic Binders	
24 899245	12" Gray floor tile Cafeteria light blue	No	30% Mineral Filler 70% Organic Binders	
25 899246	Mastic associated with #22 Lounge black	No	100% Organic Binders	
26 899247	Mastic associated with #23 Cafeteria yellow	No	100% Organic Binders	X
27 899248	Mastic associated with #24 Cafeteria yellow	No	100% Organic Binders	
28 899249	Interior stucco Cafeteria beige	Yes	<1% Chrysotile 99% Mineral Filler	
29 899250	Interior stucco beige	Yes	<1% Chrysotile 99% Mineral Filler	
30 899251	Interior stucco beige	Yes	<1% Chrysotile 99% Mineral Filler	

Sample Summary Results


Exhibit B

Date: Jul 10, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420080

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
31 899252	Exterior stucco grey	Yes	<1% Chrysotile 99% Mineral Filler	
32 899253	Exterior stucco grey	Yes	<1% Chrysotile 99% Mineral Filler	X
33 899254	Exterior stucco grey	Yes	<1% Chrysotile 99% Mineral Filler	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420094
Client Ref.: 103921 Oxnard Union HS
Port Hueneme HS - Bldg. I

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 9 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
BG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420094

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: Daniel Gamez
Port Hueneme HS - Bldg. I

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/2/2020
Date Received: 7/8/2020
Date Analyzed: 7/14/2020
No. Samples: 9

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900368	Gravel Roofing Composite Roof black	No	5% Cellulose 5% Fibrous Glass 20% Mineral Filler 70% Organic Binders	
02 900369	Gravel Roofing Composite Roof black	No	5% Cellulose 5% Fibrous Glass 20% Mineral Filler 70% Organic Binders	
03 900370	Gravel Roofing Composite Roof black	No	5% Cellulose 5% Fibrous Glass 20% Mineral Filler 70% Organic Binders	
04 900371	Penetration Mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	X
05 900372	Penetration Mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	
06 900373	Penetration Mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	

Sample Summary Results

Exhibit B


Date: Jul 17, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420094

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
07 900374	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
08 900375	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
09 900376	HVAC Duct Mastic Roof grey	No	100% Organic Binders	

Microscopist: _____



The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	6/29/20
Client:	oxnard Union HS
Site:	Pat Huememe HS - Bldg I
Project #:	103921
Inspector(s):	A. Sam / M. Hajdan

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Fissured ACT	Cafeteria		~ 5,820 #		N	G
2	↓	↓		↓			
3		Kitchen					
4	Marble associated with 12 ACT	Cafeteria					
5	↓	↓					
6		Kitchen					
7	2'x4' Fissured ACP	Lounge		~ 1,200 #			
8	↓	↓		↓			
9		↓		↓			
10	Drywall	Cafeteria		~ 5800 #			
11	↓	↓		↓			
12		Kitchen					
13	Joint Compound	Cafeteria				F	
14	↓	↓		↓			
15		Kitchen					

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

JUN 30 2020
 1:30

080

TABBARA CORPORATION


Date:	6/29/20
Client:	oxnard Union HS
Site:	Pat Huememe HS - Bldg I
Project #:	103921
Inspector(s):	A. Sam / M. Hujda

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic with 4" Baseboard	Cafeteria		~ 400 LF		N	G
17	↓	↓		↓		↓	↓
18		Lounge					
19	Plaster	Lounge		~ 3600 lb			
20	↓	Kitchen		↓			
21	↓	↓		↓			
22	12" Gray Floor Tile	Lounge		~ 5,000 lb			
23	↓	Cafeteria		↓			
24	↓	↓		↓			
25	Mastic associated with #22	Lounge					
26	↓ #23	Cafeteria		↓			
27	↓ #24	↓		↓			
28	Interior Stucco	Cafeteria		~ 2,400			
29	↓			↓			
30	↓			↓			

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____



JUN 30 2020
 1:30


TABBARA CORPORATION

Date:	6/29/20
Client:	Oxnard Union HS
Site:	Pat Huememe HS - Bldg I
Project #:	103921
Inspector(s):	A. Sam / M. Nijland

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
31	Exterior stucco			~2,000 #		N	G
32	↓			↓		↓	↓
33	↓			↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

JUN 30 2020
 Aug 1:30

TABBARA CORPORATION

Date:	7/2/20
Client:	Oxnard Union HS
Site:	Port Huememe HS - Bldg I
Project #:	103921
Inspector(s):	A. Sam / M. Nijdam

* Preliminary Results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results *	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 10	ND		
2	↓	↓		↓	ND		
3	↓	↓		↓	ND		
4	Penetration Mastic	↓		~ 15 #	ND		
5	↓	↓		↓	ND		
6	↓	↓		↓	ND		
7	HVAC Duct Mastic	↓		~ 30 LF	ND		
8	↓	↓		↓	ND		
9	↓	↓		↓	ND		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: *[Handwritten Signature]*
 7/8/20 12:46



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 10, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420081
Client Ref.: 103921 / Building J
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 27 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420081

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building J

Microscopist: Danny Lu

Oxnard Union HS / Port Hueneme HS

July 10, 2020

Mike Tabbara

Date Collected: 6/29/2020

Tabbara Corporation

Date Received: 6/30/2020

350 N. Lantana St., Suite 224

Date Analyzed: 7/8/2020

Camarillo, CA 93010

No. Samples: 27

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899255	12" Random hole ACT Room 100 beige	No	98% Cellulose 2% Fibrous Glass	
2 899256	12" Random hole ACT Band room storage beige	No	98% Cellulose 2% Fibrous Glass	
3 899257	12" Random hole ACT Band room storage beige	No	98% Cellulose 2% Fibrous Glass	
4 899258	Mastic associated with ACT Band room storage brown	No	10% Cellulose 90% Organic Binders	
5 899259	Mastic associated with ACT Room 100 brown	No	10% Cellulose 90% Organic Binders	
6 899260	Mastic associated with ACT Band room storage brown	No	10% Cellulose 90% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420081

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899261	Drywall and joint compound composite Band room storage white	No	10% Cellulose 90% Mineral Filler	
8 899262	Drywall and joint compound composite Band room storage white	No	10% Cellulose 90% Mineral Filler	
9 899263	Drywall and joint compound composite Room 100 white	No	10% Cellulose 90% Mineral Filler	X
10 899264	Mastic associated with 4" BB Room 100 tan	No	100% Organic Binders	
11 899265	Mastic associated with 4" BB Room 101 tan	No	100% Organic Binders	
12 899266	Mastic associated with 4" BB Room 101 tan	No	100% Organic Binders	
13 899267	12" Tan floor tile Room 101A hall white	No	100% Organic Binders	
14 899268	12" Tan floor tile Room 100 white	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420081

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899269	12" Tan floor tile Room 100 white	No	100% Organic Binders	
16 899270	Mastic associated with #13 Room 101A hall black	No	100% Organic Binders	X
17 899271	Mastic associated with #14 Room 100 black	No	100% Organic Binders	
18 899272	Mastic associated with #15 Room 100 black	No	100% Organic Binders	
19 899273	12" Gray floor tile Band room 101 grey	No	100% Organic Binders	
20 899274	12" Gray floor tile Band room 101 grey	No	100% Organic Binders	
21 899275	12" Gray floor tile Band room office grey	No	100% Organic Binders	
22 899276	Mastic associated with #19 brown	No	5% Cellulose 95% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 10, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420081

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899277	Mastic associated with #20 brown	No	5% Cellulose 95% Organic Binders	
24 899278	Mastic associated with #21 brown	No	5% Cellulose 95% Organic Binders	
25 899279	Stucco Exterior walls grey/purple	No	100% Mineral Filler	
26 899280	Stucco Exterior walls grey/purple	No	100% Mineral Filler	X
27 899281	Stucco Exterior walls grey/purple	No	100% Mineral Filler	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420096
Client Ref.: 103921 / Building J
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420096

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building J Microscopist: Vy Phan
Oxnard Union HS / Port Hueneme HS

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/8/2020
Date Analyzed: 7/10/2020
No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900526	Gravel roofing composite Roof black	No	15% Cellulose 30% Fibrous Glass 15% Mineral Filler 40% Organic Binders	
2 900527	Gravel roofing composite Roof black	No	15% Cellulose 30% Fibrous Glass 15% Mineral Filler 40% Organic Binders	
3 900528	Gravel roofing composite Roof black	No	15% Cellulose 30% Fibrous Glass 15% Mineral Filler 40% Organic Binders	
4 900529	Penetration mastic Roof black	No	30% Cellulose 70% Organic Binders	
5 900530	Penetration mastic Roof black	No	30% Cellulose 70% Organic Binders	
6 900531	Penetration mastic Roof black	No	30% Cellulose 70% Organic Binders	X

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Vy Phan

Micron Ref. No.: 14420096

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: Vy Phan

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	6/29/20
Client:	Oxnard Union HS
Site:	Pat Huememe HS - Bldg J
Project #:	103921
Inspector(s):	A. Sam / M. Hujdan

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Room 100		~ 4,200 lbs			
2	↓	Bond Room Storage		↓			
3	↓	↓		↓			
4	Mastic associated with ACT	Bond Room Storage		↓			
5	↓	Room 100		↓			
6	↓	Bond Room Storage		↓			
7	Daywall and Joint Compound Composite	↓		~ 4,200 lbs			
8	↓	↓		↓			
9	↓	Room 100		↓			
10	Mastic associated with 4" BB	Room 100					
11	↓	Room 101					
12	↓	Room 101					
13	12" Tam Floor Tile	Room 101A	Hall				
14	↓	Room 100					
15	↓	↓					

NA = Not Analyzed, **Friability Codes:** Nf = Non-Friable; F = Friable
 ND = Not Detected, **Condition Codes:** G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 July 1:30
 JUL 30 2020


TABBARA CORPORATION

Date: 6/29/20
 Client: Oxnard Union HS
 Site: Pat Hueneme HS - Bldg J
 Project #: 103921
 Inspector(s): A. Sam / M. Hujian

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Mastic associated with /13	Room 101A	Hall				
17	↓ /14	Room 100					
18	↓ /15	↓					
19	12" Gray Floor Tile	Band Room 101					
20	↓	↓					
21	↓	Band Room office					
22	Mastic associated with /19						
23	↓ /20						
24	↓ /21						
25	Stucco	Exterior Walls					
26	↓	↓					
27	↓	↓					

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

Time: 1:30
 JUN 30 2020

0910

TABBARA CORPORATION

Date:	7/1/20
Client:	Donald Union HS
Site:	Pat Hueneme HS - Bldg 7
Project #:	103921
Inspector(s):	A. Sam / M. Hujda

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 1 #		N	G
2	↓	↓		↓		↓	↓
3							
4	Penetration Mastic			~ 5 #			
5	↓	↓		↓		↓	↓
6	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 JUL 08 2020
 July 2020



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 7, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420082
Client Ref.: 103921 / Building K (Admin)
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 24 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420082

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building K (Admin) Microscopist: Danny Lu
Oxnard Union HS / Port Hueneme HS

July 7, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/29/2020
Date Received: 6/30/2020
Date Analyzed: 7/2/2020
No. Samples: 24

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899282	12x12" Fissured ACT East hallway grey	No	60% Cellulose 40% Fibrous Glass	
2 899283	12x12" Fissured ACT West hallway grey	No	60% Cellulose 40% Fibrous Glass	
3 899284	12x12" Fissured ACT South entrance grey	No	60% Cellulose 40% Fibrous Glass	X
4 899285	Mastic associated with 12" ACT East hallway brown	No	100% Organic Binders	
5 899286	Mastic associated with 12" ACT East hallway brown	No	100% Organic Binders	
6 899287	Mastic associated with 12" ACT West hallway brown	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420082

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899288	Drywall West hallway ceiling white	No	10% Cellulose 90% Mineral Filler	X
8 899289	Drywall East hallway ceiling white	No	10% Cellulose 90% Mineral Filler	
9 899290	Drywall East hallway ceiling white	No	10% Cellulose 90% Mineral Filler	
10 899291	Plaster Hallway north white	No	100% Mineral Filler	
11 899292	Plaster Hallway NE white	No	100% Mineral Filler	
12 899293	Plaster Admin. south entrance white	No	100% Mineral Filler	
13 899294	Mastic with 4" baseboard Admin. north tan	No	100% Organic Binders	
14 899295	Mastic with 4" baseboard East hallway tan	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420082

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899296	Mastic with 4" baseboard Nurse office tan	No	100% Organic Binders	
16 899297	12" Tan floor tile composite Hall east blue/white	No	100% Organic Binders	
17 899298	12" Tan floor tile composite Admin. middle, reception blue/white	No	100% Organic Binders	
18 899299	12" Tan floor tile composite South entrance blue/white	No	100% Organic Binders	
19 899300 Positive Stop	Mastic associated with #16 black/yellow	Yes	2% Chrysotile 8% Cellulose 90% Organic Binders	
22 899301 Positive Stop	9x9" Floor tile Vault brown	Yes	3% Chrysotile 97% Organic Binders	X
25 899302 Positive Stop	Black mastic associated with #22 Vault black	Yes	3% Chrysotile 97% Organic Binders	
28 899303	Stucco Exterior walls grey/pink	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420082

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
29 899304	Stucco Exterior walls grey/pink	No	100% Mineral Filler	
30 899305	Stucco Exterior walls grey/pink	No	100% Mineral Filler	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420097
Client Ref.: 103921 Oxnard Union HS
Port Hueneme HS - Bldg. K (Admin)

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
BG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420097

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: David Espique
Port Hueneme HS - Bldg. K (Admin)

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/8/2020
Date Analyzed: 7/17/2020
No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900532	Gravel Roofing Roof black, grey	No	10% Cellulose 5% Fibrous Glass 40% Mineral Filler 45% Organic Binders	X
02 900533	Gravel Roofing Roof black, grey	No	10% Cellulose 5% Fibrous Glass 40% Mineral Filler 45% Organic Binders	
03 900534	Gravel Roofing Roof black, grey	No	10% Cellulose 5% Fibrous Glass 40% Mineral Filler 45% Organic Binders	
04 900535	Penetration Mastic Roof black, grey	No	10% Cellulose 55% Mineral Filler 35% Organic Binders	
05 900536	Penetration Mastic Roof black, grey	No	10% Cellulose 55% Mineral Filler 35% Organic Binders	
06 900537	Penetration Mastic Roof black, grey	No	10% Cellulose 55% Mineral Filler 35% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 17, 2020

Microscopist: David Espique

Micron Ref. No.: 14420097

Cust ID No.

Asbestos

Micron ID No. Sample Description / Color

Detected

Analytical Results

Q.C.

Microscopist: David Espique

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	6/29/20
Client:	Oxnard Union HS
Site:	Pat Huememe HS - Bldg K (Admin)
Project #:	103921
Inspector(s):	A. Sam / M. Rijdsma

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12"x12" Fissured ACT	East Hallway		~ 4,000		N	G
2	↓	West Hallway		↓			
3	↓	South Entrance		↓			
4	Mastic associated with 12" ACT	East Hallway		~ 2,000			
5	↓	↓		↓			
6	↓	West Hallway		↓			
7	Drywall	West Hallway Ceiling		↓			
8	↓	East Hallway Ceiling		↓			
9	↓	East Hallway Ceiling		↓			
10	Plaster	Hallway North		~ 2,500 lb			
11	↓	Hallway NE		↓			
12	↓	Admin South Entrance		↓			
13	Mastic with 4" Baseboard	Admin North		~ 240 lb			
14	↓	East Hallway		↓			
15	↓	Nurse office		↓			

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 JUN 30 2020 1:30

TABBARA CORPORATION

Date:	6/29/20
Client:	Donald Union HS
Site:	Port Huememe HS - Bldg K (Admin)
Project #:	103921
Inspector(s):	A. Sam / M. Hujda

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	12" Tan Floor Tile Composite	Hall / East		~ 3,300 lbs		N	G
17	↓	Admin Middle	reception	↓		↓	↓
18	↓	South Entrance		↓		↓	↓
19	Mastic associated with #16			↓		↓	↓
20	↓ #17			↓		↓	↓
21	↓ #18			↓		↓	↓
22	9"x9" Floor Tile	Vault		~ 180 lbs		↓	↓
23	↓	Storage Room		↓		↓	↓
24	↓	Janitor Room		↓		↓	↓
25	Black Mastic associated #22	Vault		↓		↓	↓
26	↓ #23	Storage Room		↓		↓	↓
27	↓ #24	Janitor Room		↓		↓	↓
28	Stucco	Exterior walls		~ 2,800 lbs		↓	↓
29	↓	↓		↓		↓	↓
30	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]

Time: 1:30
 JUN 30 2020

TABBARA CORPORATION


Date: 7/1/20
 Client: Oxnard Union HS
 Site: Pat Huememe HS - Bldg K (Admin)
 Project #: 103921
 Inspector(s): A. Sam / M. Hijdan

* Preliminary Results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results *	Friability	Condition
1	Gravel Roofing	Roof		~ 10 #	ND	N	G
2	↓	↓		↓	ND	↓	↓
3	↓	↓		↓	ND	↓	↓
4	Penetration Mastic	↓		~ 15 #	ND	↓	↓
5	↓	↓		↓	ND	↓	↓
6	↓	↓		↓	ND	↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 JUL 08 2020
 Hwy 200



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 8, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420083
Client Ref.: 103921 / Building M
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 33 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420083

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building M

Microscopist: Jiaqi Wu

Oxnard Union HS / Port Hueneme HS

July 8, 2020

Mike Tabbara

Date Collected: 6/25/2020

Tabbara Corporation

Date Received: 6/30/2020

350 N. Lantana St., Suite 224

Date Analyzed: 7/7/2020

Camarillo, CA 93010

No. Samples: 33

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899312	12x12" Random hole ACT Classroom 50 orange	No	100% Cellulose	
2 899313	12x12" Random hole ACT Classroom 54 orange	No	100% Cellulose	
3 899314	12x12" Random hole ACT Classroom 56 orange	No	100% Cellulose	
4 899315	Mastic associated with 12" ACT Room 50A brown	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	X
5 899316	Mastic associated with 12" ACT Room 50A brown	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	
6 899317	Mastic associated with 12" ACT Room 50A brown	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 8, 2020

Microscopist: Jiaqi Wu

Micron Ref. No.: 14420083

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899318	Drywall ceiling Room 50A white	No	3% Cellulose 2% Fibrous Glass 95% Mineral Filler	
8 899319	Drywall ceiling Room 50A white	No	3% Cellulose 2% Fibrous Glass 95% Mineral Filler	
9 899320	Drywall ceiling Room 50A white	No	3% Cellulose 2% Fibrous Glass 95% Mineral Filler	
10 899321	Joint compound Room 50A white	No	100% Mineral Filler	X
11 899322	Joint compound Room 50A white	No	100% Mineral Filler	
12 899323	Joint compound Room 50A white	No	100% Mineral Filler	
13 899324	Plaster Custodian room white	No	100% Mineral Filler	
14 899325	Plaster Custodian room white	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 8, 2020

Microscopist: Jiaqi Wu

Micron Ref. No.: 14420083

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899326	Plaster Custodian room white	No	100% Mineral Filler	
16 899327	Drywall Classroom 48, heater closet white	No	4% Cellulose 96% Mineral Filler	
17 899328	Drywall Classroom 51, heater closet white	No	4% Cellulose 96% Mineral Filler	
18 899329	Drywall Classroom 54, heater closet white	No	4% Cellulose 96% Mineral Filler	
19 899330	Joint compound Classroom 48, heater closet offwhite	Yes	<1% Chrysotile 99% Mineral Filler	
20 899331	Joint compound Classroom 51, heater closet offwhite	Yes	<1% Chrysotile 99% Mineral Filler	X
21 899332	Joint compound Classroom 54, heater closet offwhite	Yes	<1% Chrysotile 99% Mineral Filler	
22 899333	Mastic associated with 4" baseboard Classroom 50 yellow	No	15% Mineral Filler 85% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 8, 2020

Microscopist: Jiaqi Wu

Micron Ref. No.: 14420083

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899334	Mastic associated with 4" baseboard Classroom 54 yellow	No	15% Mineral Filler 85% Organic Binders	
24 899335	Mastic associated with 4" baseboard Classroom 56 yellow	No	13% Mineral Filler 87% Organic Binders	
25 899336	12" White floor tile Classroom 48 white	No	25% Mineral Filler 75% Organic Binders	
26 899337	12" White floor tile Classroom 54 white	No	25% Mineral Filler 75% Organic Binders	
27 899338	12" White floor tile Classroom 51 white	No	25% Mineral Filler 75% Organic Binders	
28 899339	Black mastic associated with #25 Classroom 48 black	No	15% Mineral Filler 85% Organic Binders	
29 899340	Black mastic associated with #26 Classroom 54 black	No	15% Mineral Filler 85% Organic Binders	
30 899341	Black mastic associated with #27 Classroom 51 black	No	15% Mineral Filler 85% Organic Binders	

Sample Summary Results


Exhibit B

Date: Jul 8, 2020

Microscopist: Jiaqi Wu

Micron Ref. No.: 14420083

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
31 899342	Stucco Exterior wall grey	No	100% Mineral Filler	X
32 899343	Stucco Exterior wall grey	No	100% Mineral Filler	
33 899344	Stucco Exterior wall grey	No	100% Mineral Filler	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420098
Client Ref.: 103921 Oxnard Union HS
Port Hueneme- Bldg. M

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/9/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420098

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: Jiaqi Wu
Port Hueneme- Bldg. M

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020
Date Received: 7/9/2020
Date Analyzed: 7/15/2020
No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900538	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 80% Organic Binders	X
02 900539	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 80% Organic Binders	
03 900540	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 80% Organic Binders	
04 900541	Penetration Mastic Roof black	No	5% Cellulose 10% Fibrous Glass 85% Organic Binders	
05 900542	Penetration Mastic Roof black	No	5% Cellulose 10% Fibrous Glass 85% Organic Binders	
06 900543	Penetration Mastic Roof black	No	5% Cellulose 10% Fibrous Glass 85% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: Jiaqi Wu

Micron Ref. No.: 14420098

Cust ID No.


Asbestos

Detected

Analytical Results

Q.C.

Micron ID No. Sample Description / Color

Microscopist:  _____

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

003

TABBARA CORPORATION


Date: 6/25/20
Client: Oxnard Union HS
Site: Port Hueneume HS - Bldg M
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12"x12" Random Hole ACT	Classroom 50		~ 13,200 #		N	G
2	↓	Classroom 54		↓		↓	↓
3	↓	Classroom 56		↓		↓	↓
4	Mastic associated with 12" ACT	Room 50A		~ 700 #		↓	↓
5	↓	↓		↓		↓	↓
6	↓	↓		↓		↓	↓
7	Dry wall ceiling	Room 50A		~ 700 #		↓	↓
8	↓	↓		↓		↓	↓
9	↓	↓		↓		↓	↓
10	Joint compound	↓		↓		F	↓
11	↓	↓		↓		↓	↓
12	↓	↓		↓		↓	↓
13	Plaster	Custodian Room		~ 900 #		N	↓
14	↓	↓		↓		↓	↓
15	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____



JUN 30 2020
 11:30


TABBARA CORPORATION

Date: 6/25/20
Client: Oxnard Union HS
Site: Port Hueneume HS - Bldg M
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	Daywall	Classroom 48	Heater Closet	~ 1,200 lb		N	G
17	↓	↓ 51	↓	↓		↓	↓
18	↓	↓ 54	↓	↓		↓	↓
19	Joint Compound	Classroom 48	↓	↓		F	↓
20	↓	↓ 51	↓	↓		↓	↓
21	↓	↓ 54	↓	↓		↓	↓
22	Mastic associated with 4" Baseboard	Classroom 50		~ 1,500 LF		N	↓
23	↓	↓ 54		↓		↓	↓
24	↓	↓ 56		↓		↓	↓
25	12" White Floor Tile	Classroom 48		~ 13,200 lb			↓
26	↓	↓ 54		↓		↓	↓
27	↓	↓ 51		↓		↓	↓
28	Black Mastic associated with 25	48		↓		↓	↓
29	↓	↓ 54		↓		↓	↓
30	↓	↓ 51		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

JUN 30 2020
 11:30



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 7, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420084
Client Ref.: 103921 / Building N
Oxnard Union HS / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 24 bulk samples received by this laboratory on 6/30/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420084

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building N

Microscopist: Danny Lu

Oxnard Union HS / Port Hueneme HS

July 7, 2020

Mike Tabbara

Date Collected: 6/26/2020

Tabbara Corporation

Date Received: 6/30/2020

350 N. Lantana St., Suite 224

Date Analyzed: 7/1/2020

Camarillo, CA 93010

No. Samples: 24

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 899345	12" Random hole ACT Classroom 67 brown	No	90% Cellulose 10% Organic Binders	
2 899346	12" Random hole ACT Classroom 64 brown	No	90% Cellulose 10% Organic Binders	
3 899347	12" Random hole ACT Classroom 57 brown	No	90% Cellulose 10% Organic Binders	
4 899348	Drywall Classroom 68 white	No	8% Cellulose 2% Fibrous Glass 90% Mineral Filler	
5 899349	Drywall Classroom 61 white	No	8% Cellulose 2% Fibrous Glass 90% Mineral Filler	
6 899350	Drywall Classroom 64 white	No	8% Cellulose 2% Fibrous Glass 90% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420084

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 899351	Joint compound Classroom 68 tan	Yes	<1% Chrysotile 99% Mineral Filler	X
8 899352	Joint compound Classroom 61 tan	Yes	<1% Chrysotile 99% Mineral Filler	
9 899353	Joint compound Classroom 64 tan	Yes	<1% Chrysotile 99% Mineral Filler	
10 899354	Plaster / Gypsum composite Passage room 69A grey/white	No	10% Cellulose 90% Mineral Filler	
11 899355	Plaster / Gypsum composite Passage room 69A grey/white	No	10% Cellulose 90% Mineral Filler	
12 899356	Plaster / Gypsum composite Passage room 69A grey/white	No	10% Cellulose 90% Mineral Filler	
13 899357	Mastic associated with 4" BB Classroom 61 tan	No	100% Organic Binders	
14 899358	Mastic associated with 4" BB Classroom 57 tan	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420084

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 899359	Mastic associated with 4" BB Classroom 67 tan	No	100% Organic Binders	
16 899360	12" Tan floor tile Classroom 59 white	No	100% Organic Binders	
17 899361	12" Tan floor tile Classroom 61 white	No	100% Organic Binders	
18 899362	12" Tan floor tile Classroom 67 white	No	100% Organic Binders	
19 899363	Black mastic associated with #16 Classroom 59 black	No	100% Organic Binders	
20 899364	Black mastic associated with #17 Classroom 61 black	No	100% Organic Binders	
21 899365	Black mastic associated with #18 Classroom 67 black	No	100% Organic Binders	
22 899366	Stucco Exterior walls grey/white	No	100% Mineral Filler	X

Sample Summary Results

Exhibit B

Date: Jul 7, 2020

Microscopist: Danny Lu

Micron Ref. No.: 14420084

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 899367	Stucco Exterior walls grey/white	No	100% Mineral Filler	
24 899368	Stucco Exterior walls grey/white	No	100% Mineral Filler	

Microscopist: Danny Lu

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420099
Client Ref.: 103921 Oxnard Union HS
Port Hueneme- Bldg. N

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 6 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420099

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS Microscopist: Daniel Gamez
Port Hueneme- Bldg. N

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/1/2020

Date Received: 7/8/2020

Date Analyzed: 7/15/2020

No. Samples: 6

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900544	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
02 900545	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
03 900546	Gravel Roofing Composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
04 900547	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	X
05 900548	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
06 900549	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420099

Cust ID No.

Asbestos


Detected

Analytical Results

Q.C.

Micron ID No.

Sample Description / Color

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04


TABBARA CORPORATION

Date: 6/26/20
Client: Oxnard Union HS
Site: Port Hueneme HS - Bldg N
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition			
1	12" Random Hole ACT	Classroom 67		~ 15,600 #		N	G			
2	↓	↓ 64		↓		↓				
3		↓ 57								
4		Classroom 68						~ 1,300 #		
5	Drywall	↓ 61		↓		↓				
6		↓ 64								
7		Joint Compound	↓ 68							
8		↓ 61								
9	↓	↓ 64		↓		↓				
10		Plaster / Gypsum Composite	Passage Room 69A					~ 800 #	N	
11	↓	↓		↓		↓				
12										
13								Mastic associated with 4" BB	Classroom 61	~ 1,800 LF
14								↓ 57		
15								↓ 67		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 JUN 30 2020
 1:30

TABBARA CORPORATION

Date: 6/26/20
Client: Oxnard Union HS
Site: Port Huenehine HS - Bldg N
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	12" Tan Floor Tile	Classroom 59		~15,600 lb		N	G
17	↓	↓ 61		↓		↓	↓
18	↓	↓ 67		↓		↓	↓
19	Black Mastic associated / 16	Classroom 59		↓		↓	↓
20	with " / 17	↓ 61		↓		↓	↓
21	↓ / 18	↓ 67		↓		↓	↓
22	Stucco	Exterior Walls		~ lb		↓	↓
23	↓	↓		↓		↓	↓
24	↓	↓		↓		↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

JUN 30 2020
 11:30

099


TABBARA CORPORATION

Date:	7/1/20
Client:	Oxnard Union HS
Site:	Port Hueneeme HS - Bldg N
Project #:	103921
Inspector(s):	A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	Gravel Roofing Composite	Roof		~		N	G
2	↓	↓				↓	↓
3							
4	Penetration Mastic			~20 #			
5	↓	↓		↓		↓	↓
6							
7							

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 

JUL 08 2020
 Aug 2020



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420100
Client Ref.: 103921 / Building O
Oxnard Union HS / Port Hueneme

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 27 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420100

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building O Microscopist: Daniel Gamez
Oxnard Union HS / Port Hueneme

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 6/30/2020
Date Received: 7/8/2020
Date Analyzed: 7/11/2020
No. Samples: 27

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900550	12" Random hole ACT Room 70A brown	No	100% Cellulose	
2 900551	12" Random hole ACT Room 71 brown	No	100% Cellulose	
3 900552	12" Random hole ACT Room 72 brown	No	100% Cellulose	
4 900553	2x4' Fissured ACP Room 72 office beige	No	60% Cellulose 20% Fibrous Glass 20% Mineral Filler	X
5 900554	2x4' Fissured ACP Room 72 office beige	No	60% Cellulose 20% Fibrous Glass 20% Mineral Filler	
6 900555	2x4' Fissured ACP Room 72 office beige	No	60% Cellulose 20% Fibrous Glass 20% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420100

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900556	Drywall Room 70A white	No	100% Mineral Filler	
8 900557	Drywall Room 70A white	No	100% Mineral Filler	
9 900558	Drywall Room 71 white	No	100% Mineral Filler	
10 900559	Joint compound Room 70A beige	Yes	<1% Chrysotile 99% Mineral Filler	
11 900560	Joint compound Room 70A white	No	100% Mineral Filler	X
12 900561	Joint compound Room 71 beige	Yes	<1% Chrysotile 99% Mineral Filler	
13 900562	Mastic with 4" baseboard Room 70A yellow	No	100% Organic Binders	
14 900563	Mastic with 4" baseboard Room 70B yellow	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420100

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900564	Mastic with 4" baseboard Room 72 yellow	No	100% Organic Binders	
16 900565	12" Tan floor tile Room 70A beige	No	100% Mineral Filler	
17 900566	12" Tan floor tile Room 70B beige	No	100% Mineral Filler	
18 900567	12" Tan floor tile Room 72 beige	No	100% Mineral Filler	
19 900568	Black mastic associated with #16 black	No	100% Organic Binders	
20 900569	Black mastic associated with #17 black	No	100% Organic Binders	
21 900570	Black mastic associated with #18 black	No	100% Organic Binders	
22 900571	Gravel roofing composite Roof black	No	5% Cellulose 10% Fibrous Glass 35% Mineral Filler 50% Organic Binders	

Sample Summary Results


Exhibit B

Date: Jul 14, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420100

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
23 900572	Gravel roofing composite Roof black	No	5% Cellulose 10% Fibrous Glass 35% Mineral Filler 50% Organic Binders	
24 900573	Gravel roofing composite Roof black	No	5% Cellulose 10% Fibrous Glass 35% Mineral Filler 50% Organic Binders	X
25 900574	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
26 900575	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
27 900576	Penetration mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneeme - Bldg 0
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Room 70B				N	G
2	↓	71				↓	↓
3	↓	72				↓	↓
4	2'x4' Fissured ACP	Room 72 office				↓	↓
5	↓	↓				↓	↓
6	↓	↓				↓	↓
7	↓ Drywall	Room 70A				↓	↓
8	↓	Room 70A				↓	↓
9	↓	71				↓	↓
10	↓ Joint Compound	Room 70A				F	↓
11	↓	Room 70A				↓	↓
12	↓	71				↓	↓
13	↓ Tastic with 4" Baseboard	70A				N	↓
14	↓	70B				↓	↓
15	↓	72				↓	↓

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 JUL 08 2020
 Aug 2020


TABBARA CORPORATION

Date: 6/30/20
Client: Oxnard Union HS
Site: Port Hueneume - Bldg 0
Project #: 103921
Inspector(s): A. Sam / M. Majdoub

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
16	12" Tan Floor Tile	Room 70A				N	G
17	↓	↓				↓	↓
18		70B					
19	Black Mastic associated /16	↓					
20	↓ /17						
21	↓ /18						
22	Gravel Roofing Composite	Roof					
23	↓	↓					
24							
25	Penetration Mastic			~10 #			
26	↓			↓			
27	↓	↓					

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 
 JUL 08 2020
 Aug 2:00



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420101
Client Ref.: 103921 Oxnard Union HSD
Port Hueneme HS - Bldg P

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 18 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.

For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
NO



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420101

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HSD Microscopist: David Soliman
Port Hueneme HS - Bldg P

July 16, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/6/2020
Date Received: 7/8/2020
Date Analyzed: 7/15/2020
No. Samples: 18

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900577	Drywall Entrance Hall white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
2 900578	Drywall Entrance Hall white	No	1% Cellulose 1% Fibrous Glass 98% Mineral Filler	
3 900579	Drywall Entrance Hall white, brown	No	4% Cellulose 1% Fibrous Glass 95% Mineral Filler	
4 900580	Joint Compound Entrance Hall white	No	100% Mineral Filler	X
5 900581	Joint Compound Entrance Hall white	No	100% Mineral Filler	
6 900582	Joint Compound Entrance Hall white	No	100% Mineral Filler	

Sample Summary Results

Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420101

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900583	Plaster Entrance Hall to Court white	No	100% Mineral Filler	
8 900584	Plaster Entrance Hall to Court white	No	100% Mineral Filler	
9 900585	Plaster Entrance Hall to Court white	No	100% Mineral Filler	
10 900586	Mastic with 4" Baseboard Front Entrance white	No	10% Mineral Filler 90% Organic Binders	
11 900587	Mastic with 4" Baseboard Front Entrance white	No	10% Mineral Filler 90% Organic Binders	
12 900588	Mastic with 4" Baseboard Front Entrance white	No	10% Mineral Filler 90% Organic Binders	
13 900589	Gravel Roofing Composite Lower Roof black, brown	No	5% Cellulose 5% Fibrous Glass 50% Mineral Filler 40% Organic Binders	X
14 900590	Gravel Roofing Composite Lower Roof black, brown	No	5% Cellulose 5% Fibrous Glass 50% Mineral Filler 40% Organic Binders	

Sample Summary Results


Exhibit B

Date: Jul 16, 2020

Microscopist: David Soliman

Micron Ref. No.: 14420101

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900591	Gravel Roofing Composite Lower Roof black, brown	No	25% Cellulose 5% Fibrous Glass 40% Mineral Filler 30% Organic Binders	
16 900592	Penetration Mastic Lower Roof black, white, brown	No	5% Cellulose 45% Mineral Filler 50% Organic Binders	
17 900593	Penetration Mastic Lower Roof black, white	No	5% Cellulose 45% Mineral Filler 50% Organic Binders	
18 900594	Penetration Mastic Lower Roof black, white	No	5% Cellulose 45% Mineral Filler 50% Organic Binders	

Microscopist:  _____

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date:	7/6/20
Client:	Oxnard Union HS District
Site:	Port Huememe HS - Bldg P (Gym)
Project #:	103921
Inspector(s):	RT/STJ/dms


* Preliminary Result

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results *	Friability	Condition
1	Drywall	Entrance Hall	Ceiling	~1,200 lbs	ND	N	G
2			Walls RR		ND		
3			Concession		ND		
4	Joint Compound	Entrance Hall	RR walls	~1,200 lbs	ND	F	
5					ND		
6			Concession		ND		
7	Plaster	Entrance Hall		~1,000 lbs	ND	N	
8		To Court			ND		
9					ND		
10	Mastic with 4" Baseboard	Front Entrance		~120 LF	ND		
11					ND		
12					ND		
13	Gravel Roofing Composite	Lower Roof		~2,400 #	ND		
14					ND		
15					ND		

NA = Not Analyzed, **Friability Codes:** Nf = Non-Friable; F = Friable
 ND = Not Detected, **Condition Codes:** G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____



JUL 08 2020
 Aug 200



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420102
Client Ref.: 103921 / Building Q
Oxnard Union HS District / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 21 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116
NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420102

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building Q
Oxnard Union HS District / Port Hueneme HS

Microscopist: Daniel Gamez

July 15, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/6/2020

Date Received: 7/8/2020

Date Analyzed: 7/13/2020

No. Samples: 21

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900595	12" Random hole ACT Ceiling brown	No	100% Cellulose	
2 900596	12" Random hole ACT Ceiling brown	No	100% Cellulose	
3 900597	12" Random hole ACT Ceiling brown	No	100% Cellulose	
4 900598	Mastic associated with 12" ACT Ceiling brown	No	100% Organic Binders	X
5 900599	Mastic associated with 12" ACT Ceiling brown	No	100% Organic Binders	
6 900600	Mastic associated with 12" ACT Ceiling brown	No	100% Organic Binders	

Sample Summary Results

Exhibit B

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420102

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900601	Drywall / Joint compound composite Ceiling beige	No	100% Mineral Filler	
8 900602	Drywall / Joint compound composite Ceiling beige	No	100% Mineral Filler	
9 900603	Drywall / Joint compound composite Ceiling beige	No	100% Mineral Filler	
10 900604	Plaster Walls beige	No	100% Mineral Filler	
11 900605	Plaster Walls beige/white	No	100% Mineral Filler	
12 900606	Plaster Walls beige/white	No	100% Mineral Filler	
13 900607	Stucco Exterior walls beige/grey	Yes	<1% Chrysotile 99% Mineral Filler	X
14 900608	Stucco Exterior walls beige/grey	Yes	<1% Chrysotile 99% Mineral Filler	


Sample Summary Results

Date: Jul 15, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420102

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900609	Stucco Exterior walls beige/grey	Yes	<1% Chrysotile 99% Mineral Filler	
16 900610	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
17 900611	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
18 900612	Gravel roofing composite Roof black	No	10% Cellulose 10% Fibrous Glass 40% Mineral Filler 40% Organic Binders	
19 900613	Penetration mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	X
20 900614	Penetration mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	
21 900615	Penetration mastic Roof black	No	20% Cellulose 20% Mineral Filler 60% Organic Binders	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 7/6/20
 Client: Oxnard Union HS District
 Site: Port Hueneme HS / BLDG Q
 Project #: 103921
 Inspector(s): A. Sam / Majors

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	Ceiling		~ 3,375 lb		N	G
2	↓	↓		↓		↓	↓
3							
4	Mastic associated with 12" ACT						
5	↓						
6							
7	Daywall & Joint Compound			~ 3,375 lb		F	
8	Composites						
9	↓						
10	Plaster	Walls		~ 3,000 lb		N	
11	↓	↓					
12							
13	Stucco	Exterior Walls		~ 3,000 lb			
14	↓	↓					
15							

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 JUL 08 2020
 Prof 8 2:00



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420103
Client Ref.: 103921 / Building R (Weight Room)
Oxnard Union HS District / Port Hueneme HS

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 21 bulk samples received by this laboratory on 7/8/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
MC



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420103

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 / Building R (Weight Room)
Oxnard Union HS District / Port Hueneme HS

Microscopist: David Espique

July 14, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/6/2020

Date Received: 7/8/2020

Date Analyzed: 7/12/2020

No. Samples: 21

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
1 900616	12" Random hole ACT Ceiling tan/white	No	85% Cellulose 15% Organic Binders	
2 900617	12" Random hole ACT Ceiling tan	No	100% Cellulose	
3 900618	12" Random hole ACT Ceiling tan/white	No	85% Cellulose 15% Organic Binders	
4 900619	Mastic with 12" ACT Ceiling brown	No	10% Mineral Filler 90% Organic Binders	
5 900620	Mastic with 12" ACT Ceiling brown	No	10% Mineral Filler 90% Organic Binders	
6 900621	Mastic with 12" ACT Ceiling brown	No	10% Mineral Filler 90% Organic Binders	X

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: David Espique

Micron Ref. No.: 14420103

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
7 900622	Drywall / Joint compound composite Ceiling white/brown/beige	Yes	<1% Chrysotile 7% Cellulose 1% Fibrous Glass 91% Mineral Filler	
8 900623	Drywall / Joint compound composite Ceiling white/brown/beige	Yes	<1% Chrysotile 7% Cellulose 1% Fibrous Glass 91% Mineral Filler	
9 900624	Drywall / Joint compound composite Ceiling white/brown/beige	Yes	<1% Chrysotile 7% Cellulose 1% Fibrous Glass 91% Mineral Filler	
10 900625	Plaster Walls grey	No	100% Mineral Filler	
11 900626	Plaster Walls grey	No	100% Mineral Filler	
12 900627	Plaster Walls grey	No	100% Mineral Filler	
13 900628	Stucco Exterior walls offwhite/grey	Yes	<1% Chrysotile 99% Mineral Filler	
14 900629	Stucco Exterior walls offwhite/grey	Yes	<1% Chrysotile 99% Mineral Filler	X

Sample Summary Results

Exhibit B

Date: Jul 14, 2020

Microscopist: David Espique

Micron Ref. No.: 14420103

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
15 900630	Stucco Exterior walls offwhite/grey	Yes	<1% Chrysotile 99% Mineral Filler	X
16 900631	Gravel roofing composite Roof grey/black	No	20% Cellulose 5% Fibrous Glass 35% Mineral Filler 40% Organic Binders	
17 900632	Gravel roofing composite Roof grey/black	No	20% Cellulose 5% Fibrous Glass 35% Mineral Filler 40% Organic Binders	
18 900633	Gravel roofing composite Roof grey/black	No	20% Cellulose 5% Fibrous Glass 35% Mineral Filler 40% Organic Binders	
19 900634	Penetration mastic Roof grey/black	No	10% Cellulose 60% Mineral Filler 30% Organic Binders	
20 900635	Penetration mastic Roof grey/black	No	10% Cellulose 60% Mineral Filler 30% Organic Binders	
21 900636	Penetration mastic Roof grey/black	No	10% Cellulose 60% Mineral Filler 30% Organic Binders	

Microscopist: 

The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04


TABBARA CORPORATION

Date: 7/6/20
 Client: Oxnard Union HS District
 Site: Port. Hueneme HS / BLDG R (Weight Room)
 Project #: 103921
 Inspector(s): A. Sam / Majda

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results	Friability	Condition
1	12" Random Hole ACT	ceiling		~3,375 #		N	G
2	↓	↓		↓		↓	↓
3							
4	Mastic with 12" ACT						
5	↓	↓		↓		↓	↓
6							
7	Daywall & Joint Compound	ceiling		~3,375 #		F	
8	Composite	↓		↓		↓	↓
9	↓	↓		↓		↓	↓
10	Plaster	walls		~3,000 #		N	
11	↓	↓		↓		↓	↓
12							
13	Stucco	Exterior Walls		~3,000 #			
14	↓	↓		↓		↓	↓
15							

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: 



Micron Environmental Labs, Inc.

3565 Lexington Ave • El Monte, California 91731

Phone (626) 454-4782 • Fax (626) 602-9661

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Subject: PLM Analysis of Bulk Samples
Micron Job No.: 14420104
Client Ref.: 103921 Oxnard Union HS District
Port Hueneme HS - Bldg. T

Dear Mr. Tabbara:

This report includes an attached summary of the samples collected for the analyses of the 9 bulk samples received by this laboratory on 7/9/2020. The analyses were completed using polarized light microscopy (PLM) in accordance with the EPA Method 600/R-93/116, July 1993. The quantification is based on the percentage of visual area estimation and is expressed as percent area. Samples that are multilayer are analyzed by layer unless, it has been requested as a composite analysis. These visual area estimate results are based on using reference standards materials that are routinely used in the laboratory.


For all the organic matrix samples that were not asbestos detected by (PLM), Micron Environmental recommends the use of Transmission Electron Microscopy (TEM) due to the size and the masking of the fibers.


Micron Environmental Labs, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200294-0 for asbestos fiber analysis (PLM).

Micron Environmental Labs, Inc. is responsible for the accuracy in this report, but we are not liable for any wrong data given to us by the customer regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government. We will retain these samples for a period of thirty days unless otherwise specified. This report pertains only to the samples submitted and analyzed.

Micron Environmental will not grant reproduction of this report unless an approval is obtained from this laboratory. Please feel free to contact the laboratory for questions regarding results or the analytical methods used at (626)-454-4782.

Sincerely,
Micron Environmental Labs, Inc.


Daniel Gamez
Director
Attachments
BG



3565 Lexington Ave.
El Monte, CA 91731

Micron Environmental Labs, Inc.

Exhibit B

Analytical Method: EPA 600/R-93/116

NIST / NVLAP Lab Code No. 200294-0
California ELAP Certificate No. 2297

Micron Ref. No.

14420104

TEL: 626-454-4782
FAX: 626-602-9661

Sample Summary Results

Customer Project: 103921 Oxnard Union HS District Microscopist: Daniel Gamez
Port Hueneme HS - Bldg. T

July 17, 2020

Mike Tabbara
Tabbara Corporation
350 N. Lantana St., Suite 224
Camarillo, CA 93010

Date Collected: 7/6/2020
Date Received: 7/9/2020
Date Analyzed: 7/17/2020
No. Samples: 9

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
01 900637	Gravel Roofing Composite Roof black	No	5% Cellulose 10% Fibrous Glass 5% Synthetic 40% Mineral Filler 40% Organic Binders	
02 900638	Gravel Roofing Composite Roof black	No	5% Cellulose 10% Fibrous Glass 5% Synthetic 40% Mineral Filler 40% Organic Binders	
03 900639	Gravel Roofing Composite Roof black	No	5% Cellulose 10% Fibrous Glass 5% Synthetic 40% Mineral Filler 40% Organic Binders	
04 900640	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
05 900641	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	
06 900642	Penetration Mastic Roof black	No	20% Cellulose 40% Mineral Filler 40% Organic Binders	

Sample Summary Results

Exhibit B


Date: Jul 17, 2020

Microscopist: Daniel Gamez

Micron Ref. No.: 14420104

Cust ID No. Micron ID No.	Sample Description / Color	Asbestos Detected	Analytical Results	Q.C.
07 900643	HVAC Duct Mastic Roof grey	No	100% Organic Binders	X
08 900644	HVAC Duct Mastic Roof grey	No	100% Organic Binders	
09 900645	HVAC Duct Mastic Roof grey	No	100% Organic Binders	

Microscopist: _____



The limit of detection for this analytical method is less than one percent asbestos (visual area estimates). CV=0.04

TABBARA CORPORATION

Date: 7/6/20
 Client: Oxnard Union HS District
 Site: Port Hueneme HS / BLDG T
 Project #: 103921
 Inspector(s): A. Sam / Majda

* Preliminary results

ASBESTOS BULK SAMPLE FIELD LOG

Sample Number	Material Sampled	Sample Location	Location in Room	Quantity	Analytical Results*	Friability	Condition
1	Gravel Roofing Composite	Roof		~ 10	ND	N	G
2					ND		
3					ND		
4	Penetration Mastic			~ 30	ND		
5					ND		
6					ND		
7	HVAC Duct Mastic				ND		
8					ND		
9					ND		

NA = Not Analyzed, Friability Codes: Nf = Non-Friable; F = Friable
 ND = Not Detected, Condition Codes: G = Good; Fr = Fair; P = Poor
 N = Negative

Signature: _____

[Handwritten Signature]
 July 2:00
 JUL 08 2020

APPENDIX B
CERTIFICATIONS

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Amir Abbas Sam


Name



Certification No. 09-4551

Expires on 08/20/20

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



DEPARTMENT OF INDUSTRIAL RELATIONS
Division of Occupational Safety and Health
Asbestos Certification & Training Unit
2424 Arden Way, Suite 495
Sacramento, CA 95825-2417
(916) 574-2993 Office (916) 483-0572 Fax
<http://www.dir.ca.gov/dosh/asbestos.html> acru@dir.ca.gov



204053128C

237

April 03, 2019

Ivan Dean Myers
11664 Pala Mesa Dr
Porter Ranch CA 91326

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, you must abide by the rules printed on the back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card. [8 CCR 341.15(h)(1)].

Please hold and do not send copies of your required AHERA refresher renewal certificates to our office until you apply for renewal of your certification.

Certificates must be kept current if you are actively working as a CAC or CSST. The grace period is only for those who are not actively working as an asbestos consultant or site surveillance technician.

Please contact our office at the above address or email with any changes in your contact/ mailing information within 15 days of the change.

Sincerely,

Jeff Ferrell
Senior Safety Engineer

Attachment: Certification Card

cc: File

